


N/A

THS6042CDDA

Inombolo yendawo: THS6042CDDA
 Umkhqiqi / Umshicileli: N/A
 Ingcaciso yeMveliso: IC LINE DRIVER DSL 2CHAN 8SOPWR
 Maxwebhu:
 RoHS Imeko: Ukukhokela mahala / RoHS Ukuthobela
 Umkhumbi: ehong Kong
 Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS



Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA

Iinkcukacha zeTHS6042CDDA

INOMBOLO YENDAWO	THS6042CDDA
UMENZI	N/A
INKCAZO	IC LINE DRIVER DSL 2CHAN 8SOPWR
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	5 V ~ 15 V
UHLOBO	Driver
IPHAKHEJI YECANDELO LENKONZO	8-SO PowerPad
UCHUNGECHUNGE	-
PROTOCOL	DSL
PACKAGING	Tube
IPHAKHEJI / IIMEKO	8-PowerSOIC (0.154", 3.90mm Width)
UKUSHISA OKUSEBENZAYO	0°C ~ 70°C
INANI LABAQHUBI / ABAFUMANAYO	2/0
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	20 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
DUPLEX	-
INKCAZO ECACILEYO	2/0 Driver DSL 8-SO PowerPad
IXABISO LEDATHA	-
ISIQENDU SENOMBOLO YESISEKO	THS6042

Amanqaku afanayo

THS6042CDDA	Umhambisi we-THS6042CDDA	Umboneleli we-THS6042CDDA
Ixabiso le-THS6042CDDA	Imifanekiso ye-THS6042CDDA	Umfanekiso we-THS6042CDDA
Idatha ye-THS6042CDDA yePD	I-THS6042CDDA Khuphela iDatasheet	Idatha ye-THS6042CDDA
Ivenkile ye-THS6042CDDA	Thenga iTHS6042CDDA	Thenga i THS6042CDDA
THS6042CDDA	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

<p>THS6042CDDARG3 Abavelisi: N/A Inkcazo: IC LINE DRIVER DSL 2CHAN 8SOPWR Ikhona evenkileni: 5110 pcs</p> <p>RFQ</p>	<p>THS6032IVFPRG4 Abavelisi: N/A Inkcazo: IC ADSL LINE DRIVER LP 32-HLQFP Ikhona evenkileni: 5063 pcs</p> <p>RFQ</p>
<p>THS6032IVFPR Abavelisi: N/A Inkcazo: IC ADSL LINE DRIVER LP 32-HLQFP Ikhona evenkileni: 4895 pcs</p> <p>RFQ</p>	<p>THS6042CDRG4 Abavelisi: N/A Inkcazo: IC LINE DRIVER DSL 2CHAN 8SOIC Ikhona evenkileni: 5368 pcs</p> <p>RFQ</p>
<p>THS6032IVFP Abavelisi: N/A Inkcazo: IC LINE DRVR ADSL LP 32-HLQFP Ikhona evenkileni: 5178 pcs</p> <p>RFQ</p>	<p>THS6032IGQER Abavelisi: N/A Inkcazo: IC LINE DRIVER DSL 2CHAN 80BGA Ikhona evenkileni: 5910 pcs</p> <p>RFQ</p>
<p>THS6032IDWPR Abavelisi: N/A Inkcazo: IC LINE DRIVER 2CHAN 20SO-PWR Ikhona evenkileni: 12684 pcs</p> <p>RFQ</p>	<p>THS6042CDDAR Abavelisi: N/A Inkcazo: IC LINE DRIVER DSL 2CHAN 8SOPWR Ikhona evenkileni: 5551 pcs</p> <p>RFQ</p>
<p>THS6042CD Abavelisi: N/A Inkcazo: IC LINE DRIVER DSL 2CHAN 8SOIC Ikhona evenkileni: 5366 pcs</p> <p>RFQ</p>	<p>THS6042CDDAG3 Abavelisi: N/A Inkcazo: IC LINE DRIVER DSL 2CHAN 8SOPWR Ikhona evenkileni: 11117 pcs</p> <p>RFQ</p>
<p>THS6042CDR Abavelisi: N/A Inkcazo: IC LINE DRIVER DSL 2CHAN 8SOIC Ikhona evenkileni: 5428 pcs</p> <p>RFQ</p>	<p>THS6042CDG4 Abavelisi: N/A Inkcazo: IC LINE DRIVER DSL 2CHAN 8SOIC Ikhona evenkileni: 4767 pcs</p> <p>RFQ</p>