





TDK Corporation

HHM2510B1

Inombolo yendawo:
Umkhqizi / Umshicileli:
Ingcaciso yeMveliso
Maxwebhu:
RoHS Imeko
Umkhumbi
Indlela yokuthunyelwa


HHM2510B1
TDK Corporation
RF DIR COUPLER 2.4-2.5GHZ 0202
 HHM2510B1.pdf
 Ukukhokela mahala / RoHS Ukuthobela
ehong Kong
DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha zeHHM2510B1

INOMBOLO YENDAWO	HHM2510B1
UMENZI	TDK Corporation
INKCAZO	RF DIR COUPLER 2.4-2.5GHZ 0202
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	 HHM2510B1.pdf
IPHAKHEJI YECANDELO LENKONZO	0202
UCHUNGECHUNGE	*
PACKAGING	Cut Tape (CT)
IPHAKHEJI / IIMEKO	0202 (0505 Metric), 4 PC Pad
AMANYE AMAGAMA	445-175594-1
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INKCAZO ECACILEYO	RF Directional Coupler 0202 (0505 Metric), 4 PC Pad

Amanqaku afanayo

TDK Corporation HHM2510B1	Umhambisi we-HHM2510B1	Umboneleli we-HHM2510B1
Ixabiso le-HHM2510B1	Imifanekiso ye-HHM2510B1	Umfanekiso we-HHM2510B1
Idatha ye-HHM2510B1 yePD	I-HHM2510B1 Khuphela iDatasheet	Idatha ye-HHM2510B1
Ivenkile ye-HHM2510B1	Thenga iHHM2510B1	Thenga iTDK Corporation HHM2510B1
TDK Corporation HHM2510B1	Umboneleli we-TDK Corporation	Umhambisi we-TDK Corporation
TDK Corporation HHM2510B1		

Iimveliso ezihambelanayo

 <p>HHM2909C4 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 777-925MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2919A2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 2.4-2.5GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2215SA5 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 824-915MHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2319B2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 824-915MHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2915A2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2220SA3 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 1.92-1.98GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2910E1 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 1.71GHZ-2.03GHZ Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2910E4 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 1.71GHZ-1.98GHZ Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM22137A2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 698-2620MHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM22152A2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 450-3800MHZ 1608 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2917B1 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 2.4-2.5GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2293A1 Abavelisi: TDK Corporation Inkcazo: MULTILAYER DIVIDER FOR W-LAN/BLU Ikhona evenkileni: Out stock</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

