

Microsemi

MT8880CS1

Inombolo yendawo:
Umkhiziqi / Umshicileli:
Ingcaciso yeMveliso
Maxwebhu:
RoHS Imeko
Umkhumbi
Indlela yokuthunyelwa


MT8880CS1
Microsemi
IC TXRX DTMF 20SOIC
 MT8880CS1.pdf
 Ukukhokela mahala / RoHS Ukuthobela
ehong Kong
DHL/Fedex/TNT/UPS/EMS

ISICELO
SESIKATSHULWA



Umfanekiso ungunonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha zeMT8880CS1

| | |
|---------------------------------------|---|
| INOMBOLO YENDAWO | MT8880CS1 |
| UMENZI | Microsemi |
| INKCAZO | IC TXRX DTMF 20SOIC |
| ISIMO SOBUME BENKOKELI / ISIMO SEROHS | Ukukhokela mahala / RoHS Ukuthobela |
| ISHITI YEDATHA |  MT8880CS1.pdf |
| UKUNIKEZELA NGEEVOTSI | 4.75 V ~ 5.25 V |
| IPHAKHEJI YECANDELO LENKONZO | 20-SOIC |
| UCHUNGECHUNGE | - |
| PACKAGING | Tube |
| IPHAKHEJI / IIMEKO | 20-SOIC (0.295", 7.50mm Width) |
| UKUSHISA OKUSEBENZAYO | -40°C ~ 85°C |
| INANI LEESEKETHE | 1 |
| UHLOBO LOKUPHAKAMISA | Surface Mount |
| INQANABA LOKUSONDEZA UBUNINZI (MSL) | 3 (168 Hours) |
| IXESHA LENKQUBO YENKOKELI YEHLABATHI | 8 Weeks |
| ISIMO SOBUME BENKOKELI / ISIMO SEROHS | Lead free / RoHS Compliant |
| INTERFACE | - |
| NDAKANYA | - |
| UMSEBENZI | DTMF Transceiver |
| INKCAZO ECACILEYO | Telecom IC DTMF Transceiver 20-SOIC |
| UKUNIKEZELWA KWANGOKU | 7mA |

Amanqaku afanayo

| | | |
|--|---|---|
| Microsemi MT8880CS1 | Umhambisi we-MT8880CS1 | Umboneleli we-MT8880CS1 |
| Ixabiso le-MT8880CS1 | Imifanekiso ye-MT8880CS1 | Umfanekiso we-MT8880CS1 |
| Idatha ye-MT8880CS1 yePD | I-MT8880CS1 Khuphela iDatasheet | Idatha ye-MT8880CS1 |
| Ivenkile ye-MT8880CS1 | Thenga iMT8880CS1 | Thenga iMicrosemi MT8880CS1 |
| Microsemi MT8880CS1 | Umboneleli we-Microsemi | Umhambisi we-Microsemi |
| Microsemi MT8880CS1 | Microsemi Analog Mixed Signal Group MT8880CS1 | Microsemi Analog Mixed Signal Group [MIL] MT8880CS1 |
| Microsemi Consumer Medical Product Group MT8880CS1 | Microsemi HI-REL [MIL] MT8880CS1 | Microsemi Power Management Group MT8880CS1 |
| Microsemi Power Products Group MT8880CS1 | Microsemi SoC MT8880CS1 | Microsemi Commercial Components Group MT8880CS1 |
| Microsemi Corporation MT8880CS1 | Microsemi Solutions Sdn Bhd. MT8880CS1 | |

Iimveliso ezihambelanayo

| | |
|--|---|
|  <p>MT8885AE1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 20DIP Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>MT8880CPR1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 28PLCC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>MT8880CSR1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 20SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>MT8870DSR1 Abavelisi: Microsemi Inkcazo: IC RECEIVER DTMF 18SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>MT8885ANR1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 24SSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>MT8870DSR1-1 Abavelisi: Microsemi Inkcazo: IC RECEIVER DTMF 18SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>MT8888CE1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 20DIP Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>MT8885AN1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 24SSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>MT8880CP1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 28PLCC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>MT8888CN1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 24SSOP Ikhona evenkileni: 52 pcs</p> <p>RFQ</p> |
|  <p>MT8880CN1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 24SSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>MT8880CE1 Abavelisi: Microsemi Inkcazo: IC TXRX DTMF 20DIP Ikhona evenkileni: Out stock</p> <p>RFQ</p> |