




AVX Corporation

CP0805B1747CWTR

Inombolo yendawo:	CP0805B1747CWTR
Umkhqizi / Umshicileli:	AVX Corporation
Ingcaciso yeMveliso	RF DIR COUPLR 1.71-1.785GHZ 0805
Maxwebhu:	CP0805B1747CWTR.pdf
RoHS Imeko	 Iqukethe i-lead / RoHS engahambelaniyo
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha zeCP0805B1747CWTR

INOMBOLO YENDAWO	CP0805B1747CWTR
UMENZI	AVX Corporation
INKCAZO	RF DIR COUPLR 1.71-1.785GHZ 0805
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Iqukethe i-lead / RoHS engahambelaniyo
ISHITI YEDATHA	CP0805B1747CWTR.pdf
IPHAKHEJI YECANDELO LENKONZO	0805
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKELWA	-24dB
AMANDLA - UMAX	3W
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	0805 (2012 Metric)
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	10 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Contains lead / RoHS non-compliant
ISOLATION	-31dB
UKUFAKELA UKULAHLEKA	0.25dB
UKUPHINDAPHINDA	1.71GHz ~ 1.785GHz
INKCAZO ECACILEYO	RF Directional Coupler PCN 1.71GHz ~ 1.785GHz 18.5 ± 1dB 3W 0805 (2012 Metric)
FACT FACTOR	18.5 ± 1dB
UHLOBO LODIDI	Standard
IZICELO	PCN

Amanqaku afanayo

AVX Corporation CP0805B1747CWTR	Umhambisi we-CP0805B1747CWTR	Umboneleli we-CP0805B1747CWTR
Ixabiso le-CP0805B1747CWTR	Imifanekiso ye-CP0805B1747CWTR	Umfanekiso we-CP0805B1747CWTR
Idatha ye-CP0805B1747CWTR yePD	I-CP0805B1747CWTR Khuphela iDatasheet	Idatha ye-CP0805B1747CWTR
Ivenkile ye-CP0805B1747CWTR	Thenga iCP0805B1747CWTR	Thenga iAVX Corporation CP0805B1747CWTR
AVX Corporation CP0805B1747CWTR	Umboneleli we-AVX Corporation	Umhambisi we-AVX Corporation
AVX Corporation CP0805B1747CWTR	AVX Corporation [MIL] CP0805B1747CWTR	

Iimveliso ezihambelanayo

 <p>CP0805B1880AWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.85-1.91GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0805B1747AWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.71-1.785GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0805B1747BWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.71-1.785GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0805B1842AWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.805-1.88GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0805B1100CWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.1GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0805B1765AWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.765GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0805B1880BWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.85-1.91GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0805B1441AWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.429-1.453GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0805B1741AWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.741GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0805B1441CWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.429-1.453GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0805B1842BWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.805-1.88GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0805B1842CWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLR 1.805-1.88GHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

