



Intersil

## X4005M8I-2.7

Inombolo yendawo: X4005M8I-2.7

Umkhqizi / Umshicileli: Intersil

Ingcaciso yeMveliso IC SUPERVISOR CPU I2C 8-MSOP

Maxwebhu: [PDF X4005M8I-2.7.pdf](#)

RoHS Imeko  Iqukethe i-lead / RoHS engahambelaniyo

Umkhumbi ehong Kong

Indlela yokuthunyelwa DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

### Iinkcukacha zeX4005M8I-2.7

INOMBOLO YENDAWO	X4005M8I-2.7
UMENZI	Intersil
INKCAZO	IC SUPERVISOR CPU I2C 8-MSOP
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Iqukethe i-lead / RoHS engahambelaniyo
ISHITI YEDATHA	<a href="#">PDF X4005M8I-2.7.pdf</a>
I-VOLTAGE - THRESHOLD	2.62V
UHLOBO	Simple Reset/Power-On Reset
IPHAKHEJI YECANDELO LENKONZO	8-MSOP
UCHUNGECHUNGE	-
HLELA KWAKHONA IXESHA	100 ms Minimum
HLELA KWAKHONA	Active High
PACKAGING	Tube
IPHAKHEJI / IIMEKO	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
ISIPHUMO	Open Drain or Open Collector
UKUSHISA OKUSEBENZAYO	-40°C ~ 85°C (TA)
INANI LEEMIQLULU EKHANGELWEYO	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Contains lead / RoHS non-compliant
INKCAZO ECACILEYO	Supervisor Open Drain or Open Collector 1 Channel 8-MSOP
ISIQENDU SENOMBOLO YESISEKO	X4005

### Amanqaku afanayo

Intersil X4005M8I-2.7	Umhambisi we-X4005M8I-2.7	Umboneleli we-X4005M8I-2.7
Ixabiso le-X4005M8I-2.7	Imifanekiso ye-X4005M8I-2.7	Umfanekiso we-X4005M8I-2.7
Idatha ye-X4005M8I-2.7 yePD	I-X4005M8I-2.7 Khuphela iDatasheet	Idatha ye-X4005M8I-2.7
Ivenkile ye-X4005M8I-2.7	Thenga iX4005M8I-2.7	Thenga iIntersil X4005M8I-2.7
Intersil X4005M8I-2.7	Umboneleli we-Intersil	Umhambisi we-Intersil
Intersil X4005M8I-2.7		

### Iimveliso ezihambelanayo

 <p><b>X4003S8Z-4.5A</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-SOIC Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>X4005M8</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>X4005M8I</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>X4005M8IZ-2.7A</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>X4005M8-4.5A</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>X4005M8IZ-4.5A</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>X4005M8I-2.7A</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>X4005M8-2.7</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>X4005M8I-4.5A</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>X4005M8IZ-2.7</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>X4005M8IZ</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>X4005M8-2.7A</b> Abavelisi: Intersil Inkcazo: IC SUPERVISOR CPU I2C 8-MSOP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

