


N/A

CDCS504TPWRQ1

Inombolo yendawo:	CDCS504TPWRQ1
Umkhqizi / Umshicileli:	N/A
Ingcaciso yeMveliso	CLOCK FREQUENCY MULTIPLIER
Maxwebhu:	
RoHS Imeko	Ukukhokela mahala / RoHS Ukuthobela
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS



No Picture

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA

Iinkcukacha zeCDCS504TPWRQ1

INOMBOLO YENDAWO	CDCS504TPWRQ1
UMENZI	N/A
INKCAZO	CLOCK FREQUENCY MULTIPLIER
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	3 V ~ 3.6 V
UHLOBO	Multiplier
IPHAKHEJI YECANDELO LENKONZO	8-TSSOP
UCHUNGECHUNGE	Automotive, AEC-Q100
UKULINGANISWA - UKUFAKA: ISIPHUMO	1:1
PACKAGING	Cut Tape (CT)
IPHAKHEJI / IIMEKO	8-TSSOP (0.173", 4.40mm Width)
ISIPHUMO	LVC MOS
AMANYE AMAGAMA	296-49596-1
UKUSHISA OKUSEBENZAYO	-40°C ~ 105°C
INANI LEESEKETHE	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	3 (168 Hours)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INPUT	LVC MOS
UKUPHINDAPHINDA - UMAX	108MHz
UKWAHLULA - INQAKU: UMPHUMO	No/No
INKCAZO ECACILEYO	Clock Multiplier IC 1:1 108MHz 8-TSSOP (0.173", 4.40mm Width)

Amanqaku afanayo

CDCS504TPWRQ1	Umhambisi we-CDCS504TPWRQ1	Umboneleli we-CDCS504TPWRQ1
Ixabiso le-CDCS504TPWRQ1	Imifanekiso ye-CDCS504TPWRQ1	Umfanekiso we-CDCS504TPWRQ1
Idatha ye-CDCS504TPWRQ1 yePD	I-CDCS504TPWRQ1 Khuphela iDatasheet	Idatha ye-CDCS504TPWRQ1
Ivenkile ye-CDCS504TPWRQ1	Thenga iCDCS504TPWRQ1	Thenga i CDCS504TPWRQ1
CDCS504TPWRQ1	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

<p>CDCU2A877ZQLT Abavelisi: N/A Inkcazo: IC PLL CLOCK DRIVER 1.8V 52-BGA Ikhona evenkileni: 18331 pcs</p> <p>RFQ</p>	<p>CDCS502PW Abavelisi: N/A Inkcazo: IC OSC CLOCK GENERATOR 8-TSSOP Ikhona evenkileni: 60530 pcs</p> <p>RFQ</p>
<p>CDCU877AGQLT Abavelisi: N/A Inkcazo: IC PLL CLOCK DRIVER 1.8V 52-BGA Ikhona evenkileni: 5996 pcs</p> <p>RFQ</p>	<p>CDCS503PW Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:1 108MHZ 8TSSOP Ikhona evenkileni: 59861 pcs</p> <p>RFQ</p>
<p>CDCS503TPWRQ1 Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:1 108MHZ 8TSSOP Ikhona evenkileni: 84146 pcs</p> <p>RFQ</p>	<p>CDCU877ARHARG4 Abavelisi: N/A Inkcazo: IC PLL CLOCK DRIVER 1.8V 40VQFN Ikhona evenkileni: 22362 pcs</p> <p>RFQ</p>
<p>CDCU877ARHAR Abavelisi: N/A Inkcazo: IC PLL CLOCK DRIVER 1.8V 40VQFN Ikhona evenkileni: 21378 pcs</p> <p>RFQ</p>	<p>CDCU2A877ZQLR Abavelisi: N/A Inkcazo: IC PLL CLOCK DRIVER 1.8V 52-BGA Ikhona evenkileni: 21535 pcs</p> <p>RFQ</p>
<p>CDCS502PWR Abavelisi: N/A Inkcazo: IC OSC CLOCK GENERATOR 8-TSSOP Ikhona evenkileni: 97003 pcs</p> <p>RFQ</p>	<p>CDCS503PWR Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:1 108MHZ 8TSSOP Ikhona evenkileni: 84749 pcs</p> <p>RFQ</p>
<p>CDCU877AGQLR Abavelisi: N/A Inkcazo: IC PLL CLOCK DRIVER 1.8V 52-BGA Ikhona evenkileni: 5841 pcs</p> <p>RFQ</p>	<p>CDCS502PERF-EVM Abavelisi: N/A Inkcazo: EVAL PERFORMANCE MOD FOR CDCS502 Ikhona evenkileni: 980 pcs</p> <p>RFQ</p>