



AVX Corporation

CP0603A2442ALTR

Inombolo yendawo:	CP0603A2442ALTR
Umkhqizi / Umshicileli:	AVX Corporation
Ingcaciso yeMveliso	RF DIR COUPLER 2.4-2.484GHZ 0603
Maxwebhu:	CP0603A2442ALTR.pdf
RoHS Imeko	 Iqukethe i-lead / RoHS engahambelaniyo
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.




Iinkcukacha zeCP0603A2442ALTR

INOMBOLO YENDAWO	CP0603A2442ALTR
UMENZI	AVX Corporation
INKCAZO	RF DIR COUPLER 2.4-2.484GHZ 0603
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Iqukethe i-lead / RoHS engahambelaniyo
ISHITI YEDATHA	CP0603A2442ALTR.pdf
IPHAKHEJI YECANDELO LENKONZO	0603
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKELWA	20dB
AMANDLA - UMAX	3W
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	0603 (1608 Metric)
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	10 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Contains lead / RoHS non-compliant
ISOLATION	-34dB
UKUFAKELA UKULAHLEKA	0.75dB
UKUPHINDAPHINDA	2.4GHz ~ 2.484GHz
INKCAZO ECACILEYO	RF Directional Coupler Wireless LAN 2.4GHz ~ 2.484GHz 11.5dB 3W 0603 (1608 Metric)
FACT FACTOR	11.5dB
UHLOBO LODIDI	Standard
IZICELO	Wireless LAN

Amanqaku afanayo

AVX Corporation CP0603A2442ALTR	Umhambisi we-CP0603A2442ALTR	Umboneleli we-CP0603A2442ALTR
Ixabiso le-CP0603A2442ALTR	Imifanekiso ye-CP0603A2442ALTR	Umfanekiso we-CP0603A2442ALTR
Idatha ye-CP0603A2442ALTR yePD	I-CP0603A2442ALTR Khuphela iDatasheet	Idatha ye-CP0603A2442ALTR
Ivenkile ye-CP0603A2442ALTR	Thenga iCP0603A2442ALTR	Thenga iAVX Corporation CP0603A2442ALTR
AVX Corporation CP0603A2442ALTR	Umboneleli we-AVX Corporation	Umhambisi we-AVX Corporation
AVX Corporation CP0603A2442ALTR	AVX Corporation [MIL] CP0603A2442ALTR	

Iimveliso ezihambelanayo

 <p>CP0603A2400GLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.4GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0603A2442AWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.4-2.484GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0603A2422DWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.422GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0603A2100BLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.1GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0603A2100DLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.1GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0603A2442BLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.4-2.484GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0603A2100FLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.1GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0603A2442BNTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.4-2.484GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0603A2442CWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.4-2.484GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0603A2442BWTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.4-2.484GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0603A2400FLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.4GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0603A2442CLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 2.4-2.484GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

