




BRN6036-0015S

Inombolo yendawo:	BRN6036-0015S
Umkhqizi / Umshicileli:	Bourns, Inc.
Ingcaciso yeMveliso	BALUN 1.2MHZ-1.7GHZ 6SMD GW
Maxwebhu:	PDF BRN6036-0015S.pdf
RoHS Imeko	 Ukukhokela mahala / RoHS Ukuthobela
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha zeBRN6036-0015S

INOMBOLO YENDAWO	BRN6036-0015S
UMENZI	Bourns, Inc.
INKCAZO	BALUN 1.2MHZ-1.7GHZ 6SMD GW
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	PDF BRN6036-0015S.pdf
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKA (MIN)	-
UHLU LWESIGABA	-
PACKAGING	Bulk
IPHAKHEJI / IIMEKO	6-SMD (5 Leads), Gull Wing
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UKUFAKELA UKULAHLEKA (MAX)	3.0dB
UKUNYAMEZELA - UKUNGALINGANI / UKULINGANISELA	-
UHLU LOLWAZI	1.2MHz ~ 1.7GHz
INKCAZO ECACILEYO	RF Balun 1.2MHz ~ 1.7GHz 6-SMD (5 Leads), Gull Wing

Amanqaku afanayo

Bourns, Inc. BRN6036-0015S	Umhambisi we-BRN6036-0015S	Umboneleli we-BRN6036-0015S
Ixabiso le-BRN6036-0015S	Imifanekiso ye-BRN6036-0015S	Umfanekiso we-BRN6036-0015S
Idatha ye-BRN6036-0015S yePD	I-BRN6036-0015S Khuphela iDatasheet	Idatha ye-BRN6036-0015S
Ivenkile ye-BRN6036-0015S	Thenga iBRN6036-0015S	Thenga iBourns, Inc. BRN6036-0015S
Bourns, Inc. BRN6036-0015S	Umboneleli we-Bourns, Inc.	Umhambisi we-Bourns, Inc.
Bourns, Inc. BRN6036-0015S	Bourns Inc. BRN6036-0015S	J.W. Miller / Bourns BRN6036-0015S

Iimveliso ezihambelanayo

 <p>BRN6036-0009S Abavelisi: Bourns, Inc. Inkcazo: BALUN 100MHZ-500MHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>BRN6036-0010S Abavelisi: Bourns, Inc. Inkcazo: BALUN 500MHZ-850MHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>BRN6044-0001S Abavelisi: Bourns, Inc. Inkcazo: BALUN 50MHZ-400MHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>BRN6036-0018S Abavelisi: Bourns, Inc. Inkcazo: BALUN 160MHZ-2.2GHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>BRN6036-0019S Abavelisi: Bourns, Inc. Inkcazo: BALUN 55MHZ-1.7GHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>BRN6036-0011S Abavelisi: Bourns, Inc. Inkcazo: BALUN 240MHZ-500MHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>BRN6036-0017S Abavelisi: Bourns, Inc. Inkcazo: BALUN 600KHZ-1.3GHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>BRN6036-0016S Abavelisi: Bourns, Inc. Inkcazo: BALUN 800KHZ-1.4GHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>BRN6036-0012S Abavelisi: Bourns, Inc. Inkcazo: BALUN 85MHZ-380MHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>BRN6036-0014S Abavelisi: Bourns, Inc. Inkcazo: BALUN 2.5MHZ-2GHZ 6SMD GULL WING Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>BRN6036-0013S Abavelisi: Bourns, Inc. Inkcazo: BALUN 5.5MHZ-850MHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>BRN6036-0020S Abavelisi: Bourns, Inc. Inkcazo: BALUN 30MHZ-1.4GHZ 6SMD GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

