



TDK Corporation

HHM2917B1

Inombolo yendawo:
Umkhqizi / Umshicileli:
Ingcaciso yeMveliso
Maxwebhu:
RoHS Imeko
Umkhumbi
Indlela yokuthunyelwa


HHM2917B1
TDK Corporation
RF DIR COUPLER 2.4-2.5GHZ 0402
 HHM2917B1.pdf
 Ukukhokela mahala / RoHS Ukuthobela
ehong Kong
DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha zeHHM2917B1

INOMBOLO YENDAWO	HHM2917B1
UMENZI	TDK Corporation
INKCAZO	RF DIR COUPLER 2.4-2.5GHZ 0402
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	 HHM2917B1.pdf
IPHAKHEJI YECANDELO LENKONZO	0402 (1005 Metric)
UCHUNGECHUNGE	HHM
UKUBUYISELA UKULAHLEKELWA	-
AMANDLA - UMAX	-
PACKAGING	Original-Reel®
IPHAKHEJI / IIMEKO	0402 (1005 Metric), 4 PC Pad
AMANYE AMAGAMA	445-172645-6
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
ISOLATION	28dB
UKUFAKELA UKULAHLEKA	0.75dB
UKUPHINDAPHINDA	2.4GHz ~ 2.5GHz
INKCAZO ECACILEYO	RF Directional Coupler 2.4GHz ~ 2.5GHz 10.8 ± 1dB 0402 (1005 Metric), 4 PC Pad
FACT FACTOR	10.8 ± 1dB
UHLOBO LODIDI	Standard
IZICELO	-

Amanqaku afanayo

TDK Corporation HHM2917B1	Umhambisi we-HHM2917B1	Umboneleli we-HHM2917B1
Ixabiso le-HHM2917B1	Imifanekiso ye-HHM2917B1	Umfanekiso we-HHM2917B1
Idatha ye-HHM2917B1 yePD	I-HHM2917B1 Khuphela iDatasheet	Idatha ye-HHM2917B1
Ivenkile ye-HHM2917B1	Thenga iHHM2917B1	Thenga iTDK Corporation HHM2917B1
TDK Corporation HHM2917B1	Umboneleli we-TDK Corporation	Umhambisi we-TDK Corporation
TDK Corporation HHM2917B1		

Iimveliso ezihambelanayo

 <p>HHM2919A2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 2.4-2.5GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2910E4 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 1.71GHZ-1.98GHZ Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2915A2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2215SA5 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 824-915MHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2933A1 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 2.4-2.5GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2319B2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 824-915MHZ 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2942A2 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 2.4-2.5GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2293A1 Abavelisi: TDK Corporation Inkcazo: MULTILAYER DIVIDER FOR W-LAN/BLU Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2909C4 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 777-925MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2910E1 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 1.71GHZ-2.03GHZ Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM2510B1 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 2.4-2.5GHZ 0202 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM2220SA3 Abavelisi: TDK Corporation Inkcazo: RF DIR COUPLER 1.92-1.98GHZ 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>