




NXP Semiconductors / Freescale

MC8640DTHX1000HE

Inombolo yendawo: MC8640DTHX1000HE
 Umkhiziqi / Umshicileli: NXP Semiconductors / Freescale
 Ingcaciso yeMveliso: IC MPU MPC86XX 1.0GHZ 1023FCCBGA
 Maxwebhu:
 RoHS Imeko: Iqukethe i-lead / RoHS engahambelaniyo
 Umkhumbi: ehong Kong
 Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS



Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO
SESIKATSHULWA

Iinkcukacha zeMC8640DTHX1000HE

INOMBOLO YENDAWO	MC8640DTHX1000HE
UMENZI	NXP Semiconductors / Freescale
INKCAZO	IC MPU MPC86XX 1.0GHZ 1023FCCBGA
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Iqukethe i-lead / RoHS engahambelaniyo
ISHITI YEDATHA	
I-VOLTAGE - I / O	1.8V, 2.5V, 3.3V
I-USB	-
IPHAKHEJI YECANDELO LENKONZO	1023-FCCBGA (33x33)
UKUKHAWULEZA	1.0GHz
UCHUNGECHUNGE	MPC86xx
IIMPAWU ZOKHUSELEKO	-
SATA	-
ABALAWULI BE-RAM	DDR, DDR2
PACKAGING	Tray
IPHAKHEJI / IIMEKO	1023-BCBGA, FCCBGA
AMANYE AMAGAMA	935319524557
UKUSHISA OKUSEBENZAYO	-40°C ~ 105°C (TA)
INANI LEECORE / UBUBANZI BEEBHASI	2 Core, 32-Bit
INQANABA LOKUSONDEZA UBUNINZI (MSL)	3 (168 Hours)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Contains lead / RoHS non-compliant
IIMPAWU ZOKWAKHEKA	No
ETHERNET	10/100/1000 Mbps (4)
ABALAWULI BEEKLAYINA KUNYE NABASEBENZI	-
INKCAZO ECACILEYO	PowerPC e600 Microprocessor IC MPC86xx 2 Core, 32-Bit 1.0GHz 1023-FCCBGA (33x33)
INKQUBO YOMSEBENZI	PowerPC e600
CO-PROCESSORS / DSP	-
ISIQENDU SENOMBOLO YESISEKO	MC8640
INTERFACES EYONGEZELELWEYO	DUART, HSSI, I ² C, RapidIO

Amanqaku afanayo

NXP Semiconductors / Freescale MC8640DTHX1000HE	Umhambisi we-MC8640DTHX1000HE	Umboneleli we-MC8640DTHX1000HE
Ixabiso le-MC8640DTHX1000HE	Imifanekiso ye-MC8640DTHX1000HE	Umfanekiso we-MC8640DTHX1000HE
Idatha ye-MC8640DTHX1000HE yePD	I-MC8640DTHX1000HE Khuphela iDatasheet	Idatha ye-MC8640DTHX1000HE
Ivenkile ye-MC8640DTHX1000HE	Thenga iMC8640DTHX1000HE	Thenga iNXP Semiconductors / Freescale MC8640DTHX1000HE
NXP Semiconductors / Freescale MC8640DTHX1000HE	Umboneleli we-NXP Semiconductors / Freescale	Umhambisi we-NXP Semiconductors / Freescale
NXP Semiconductors / Freescale MC8640DTHX1000HE	NXP Semiconductors MC8640DTHX1000HE	Freescale MC8640DTHX1000HE
Freescale Semiconductor - NXP MC8640DTHX1000HE	NXP USA Inc. MC8640DTHX1000HE	

Iimveliso ezihambelanayo

<p>MC8640DTHX1000HC Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.0GHZ 1023FCCBGA Ikhona evenkileni: Out stock RFQ</p>	<p>MC8640DHX1067NE Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.067GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>
<p>MC8640DTHX1067NC Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.067GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>	<p>MC8640DTHX1000NC Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.0GHZ 1023FCCBGA Ikhona evenkileni: Out stock RFQ</p>
<p>MC8640DTHX1250HC Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.25GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>	<p>MC8640DTVJ1000HE Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU E600 DUAL CORE 1023FCCBGA Ikhona evenkileni: Out stock RFQ</p>
<p>MC8640DHX1250HC Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.25GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>	<p>MC8640DTHX1067NE Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.067GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>
<p>MC8640DTHJ1067NE Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.067GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>	<p>MC8640DTHJ1250HE Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.25GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>
<p>MC8640DTHX1250HE Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.25GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>	<p>MC8640DHX1250HE Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC MPU MPC86XX 1.25GHZ 1023BGA Ikhona evenkileni: Out stock RFQ</p>

