



AVX Corporation

CP0402A0942BLTR


Inombolo yendawo:	CP0402A0942BLTR
Umkhqizi / Umshicileli:	AVX Corporation
Ingcaciso yeMveliso	RF DIR COUPLER 925-960MHZ 0402
Maxwebhu:	 CP0402A0942BLTR.pdf
RoHS Imeko	 Iqukethe i-lead / RoHS engahambelaniyo
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha zeCP0402A0942BLTR

INOMBOLO YENDAWO	CP0402A0942BLTR
UMENZI	AVX Corporation
INKCAZO	RF DIR COUPLER 925-960MHZ 0402
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Iqukethe i-lead / RoHS engahambelaniyo
ISHITI YEDATHA	 CP0402A0942BLTR.pdf
IPHAKHEJI YECANDELO LENKONZO	0402
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKELWA	27dB
AMANDLA - UMAX	3W
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	0402 (1005 Metric)
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	10 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Contains lead / RoHS non-compliant
ISOLATION	-46dB
UKUFAKELA UKULAHLEKA	0.25dB
UKUPHINDAPHINDA	925MHz ~ 960MHz
INKCAZO ECACILEYO	RF Directional Coupler GSM 925MHz ~ 960MHz 21dB 3W 0402 (1005 Metric)
FACT FACTOR	21dB
UHLOBO LODIDI	Standard
IZICELO	GSM

Amanqaku afanayo

AVX Corporation CP0402A0942BLTR	Umhambisi we-CP0402A0942BLTR	Umboneleli we-CP0402A0942BLTR
Ixabiso le-CP0402A0942BLTR	Imifanekiso ye-CP0402A0942BLTR	Umfanekiso we-CP0402A0942BLTR
Idatha ye-CP0402A0942BLTR yePD	I-CP0402A0942BLTR Khuphela iDatasheet	Idatha ye-CP0402A0942BLTR
Ivenkile ye-CP0402A0942BLTR	Thenga iCP0402A0942BLTR	Thenga iAVX Corporation CP0402A0942BLTR
AVX Corporation CP0402A0942BLTR	Umboneleli we-AVX Corporation	Umhambisi we-AVX Corporation
AVX Corporation CP0402A0942BLTR	AVX Corporation [MIL] CP0402A0942BLTR	

Iimveliso ezihambelanayo

 <p>CP0402A0942DLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 925-960MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0402A0942ALTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 925-960MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0402A0836ELTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 824-849MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0402A0902ALTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 890-915MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0402A0881ALTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 869-894MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0402A1441ALTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.429-1.453GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0402A0881ANTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 869-894MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0402A0836ENTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 824-849MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0402A1810CNTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.81GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0402A1842ALTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.805-1.88GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>CP0402A0947FLTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 935-960MHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>CP0402A1810BNTR Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.81GHZ 0402 Ikhona evenkileni: Out stock</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

