





Aeroflex (MACOM Technology Solutions)

MACP-009730-C60370

Inombolo yendawo: MACP-009730-C60370
 Umkhiqizi / Umshicileli: Aeroflex (MACOM Technology Solutions)
 Ingcaciso yeMveliso: RF DIR COUPLER 5MHZ-1.2GHZ MOD
 Maxwebhu: [PDF MACP-009730-C60370.pdf](#)
 RoHS Imeko:  Ukukhokela mahala / RoHS Ukuthobela
 Umkhumbi: ehong Kong
 Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

Solutions



Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA













Iinkcukacha zeMACP-009730-C60370

INOMBOLO YENDAWO	MACP-009730-C60370
UMENZI	Aeroflex (MACOM Technology Solutions)
INKCAZO	RF DIR COUPLER 5MHZ-1.2GHZ MOD
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	PDF MACP-009730-C60370.pdf
IPHAKHEJI YECANDELO LENKONZO	Module
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKELWA	23dB
AMANDLA - UMAX	250mW
PACKAGING	Cut Tape (CT)
IPHAKHEJI / IIMEKO	6-SMD Module, No Lead
AMANYE AMAGAMA	1465-1709-1
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	10 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
ISOLATION	-
UKUFAKELA UKULAHLEKA	-
UKUPHINDAPHINDA	5MHz ~ 1.2GHz
INKCAZO ECACILEYO	RF Directional Coupler General Purpose 5MHz ~ 1.2GHz 250mW 6-SMD Module, No Lead
FACT FACTOR	-
UHLOBO LODIDI	Standard
IZICELO	General Purpose

Amanqaku afanayo

Aeroflex (MACOM Technology Solutions) MACP-009730-C60370	Umhambisi we-MACP-009730-C60370	Umboneleli we-MACP-009730-C60370
Ixabiso le-MACP-009730-C60370	Imifanekiso ye-MACP-009730-C60370	Umfanekiso we-MACP-009730-C60370
Idatha ye-MACP-009730-C60370 yePD	I-MACP-009730-C60370 Khuphela iDatasheet	Idatha ye-MACP-009730-C60370
Ivenkile ye-MACP-009730-C60370	Thenga iMACP-009730-C60370	Thenga iAeroflex (MACOM Technology Solutions) MACP-009730-C60370
Aeroflex (MACOM Technology Solutions) MACP-009730-C60370	Umboneleli we-Aeroflex (MACOM Technology Solutions)	Umhambisi we-Aeroflex (MACOM Technology Solutions)
Aeroflex (MACOM Technology Solutions) MACP-009730-C60370	Aeroflex Circuit Technology MACP-009730-C60370	Aeroflex MACP-009730-C60370
Aeroflex (MACOM Technology Solutions) MACP-009730-C60370	Aeroflex Metelics, Division of MACOM MACP-009730-C60370	M/A-Com Technology Solutions MACP-009730-C60370
Metelics (MACOM Technology Solutions) MACP-009730-C60370	MACOM Technology Solutions MACP-009730-C60370	

Iimveliso ezihambelanayo

 <p>MACP-009011-C80370 Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>MACP-007727-CI07TB Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: EVAL BOARD FOR MACP-007727-CI07B Ikhona evenkileni: 1 pcs</p> <p>RFQ</p>
 <p>MACP-010507-CH0160 Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: RF DIR COUPLER 5MHZ-300MHZ 5SMD Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>MACP-010561-001SMB Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: EVAL BOARD FOR MACP-010561-TR100 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>MACP-010561-000000 Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: RF DIR COUPLER 2GHZ-6GHZ 6TDFN Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>MACP-008125-CK07TB Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: EVAL BOARD FOR MACP-008125-CK07F Ikhona evenkileni: 2 pcs</p> <p>RFQ</p>
 <p>MACP-010250-C808A0 Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: RF DIR COUPLER 5MHZ-1.2GHZ MOD Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>MACP-008125-CK07F0 Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: RF DIR COUPLER 5MHZ-1GHZ SM127 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>MACP-009596-CA01TB Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: EVAL BOARD FOR MACP-009596-CA016 Ikhona evenkileni: 13 pcs</p> <p>RFQ</p>	 <p>MACP-009596-CA0160 Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: RF DIR COUPLER 5MHZ-1GHZ SM22 Ikhona evenkileni: 460 pcs</p> <p>RFQ</p>
 <p>MACP-010414-CA0370 Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>MACP-010561-TR1000 Abavelisi: Aeroflex (MACOM Technology Solutions) Inkcazo: RF DIR COUPLER 2GHZ-6GHZ 6DFN Ikhona evenkileni: Out stock</p> <p>RFQ</p>

