



TDK Corporation


HHM1733B1

Inombolo yendawo: HHM1733B1

Umkhqizi / Umshicileli: TDK Corporation

Ingcaciso yeMveliso: BALUN 4.9GHZ-5.95GHZ 50/50 0603

Maxwebhu: [PDF HHM1733B1.pdf](#)

RoHS Imeko:  Ukukhokela mahala / RoHS Ukuthobela

Umkhumbi: ehong Kong

Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungasakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha zeHHM1733B1

INOMBOLO YENDAWO	HHM1733B1
UMENZI	TDK Corporation
INKCAZO	BALUN 4.9GHZ-5.95GHZ 50/50 0603
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	PDF HHM1733B1.pdf
UCHUNGECHUNGE	HHM
UKUBUYISELA UKULAHLEKA (MIN)	10dB
UHLU LWESIGABA	180° ±10°
PACKAGING	Cut Tape (CT)
IPHAKHEJI / IIMEKO	0603 (1608 Metric)
AMANYE AMAGAMA	445-3996-1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UKUFAKELA UKULAHLEKA (MAX)	1.2dB
UKUNYAMEZELA - UKUNGALINGANI / UKULINGANISELA	50 / 50 Ohm
UHLU LOLWAZI	4.9GHz ~ 5.95GHz
INKCAZO ECACILEYO	RF Balun 4.9GHz ~ 5.95GHz 50 / 50 Ohm 0603 (1608 Metric)

Amanqaku afanayo

TDK Corporation HHM1733B1	Umhambisi we-HHM1733B1	Umboneleli we-HHM1733B1
Ixabiso le-HHM1733B1	Imifanekiso ye-HHM1733B1	Umfanekiso we-HHM1733B1
Idatha ye-HHM1733B1 yePD	I-HHM1733B1 Khuphela iDatashet	Idatha ye-HHM1733B1
Ivenkile ye-HHM1733B1	Thenga iHHM1733B1	Thenga iTDK Corporation HHM1733B1
TDK Corporation HHM1733B1	Umboneleli we-TDK Corporation	Umhambisi we-TDK Corporation
TDK Corporation HHM1733B1		

Iimveliso ezihambelanayo

 <p>HHM1775D1 Abavelisi: TDK Corporation Inkcazo: BALUN 3.1GHZ-4.9GHZ 50/100 0805 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM1732B1 Abavelisi: TDK Corporation Inkcazo: BALUN 4.9GHZ-5.95GHZ 50/100 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM1731F1 Abavelisi: TDK Corporation Inkcazo: BALUN 1.71-1.88GHZ 50/200 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM1749S1 Abavelisi: TDK Corporation Inkcazo: BALUN 1.71-1.99GHZ 50/100 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM1752A2 Abavelisi: TDK Corporation Inkcazo: BALUN 4.9GHZ-5.95GHZ 50/200 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM1727D1 Abavelisi: TDK Corporation Inkcazo: BALUN 3.3GHZ-3.9GHZ 50/50 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM1763B2 Abavelisi: TDK Corporation Inkcazo: BALUN 880MHZ-960MHZ 50/150 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM1726N1 Abavelisi: TDK Corporation Inkcazo: BALUN 824MHZ-915MHZ 50/100 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM17168B1 Abavelisi: TDK Corporation Inkcazo: BALUN 3.4GHZ-3.8GHZ 50/50 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM1776B2 Abavelisi: TDK Corporation Inkcazo: BALUN 824MHZ-894MHZ 50/50 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>HHM1726P1 Abavelisi: TDK Corporation Inkcazo: BALUN 880MHZ-960MHZ 50/100 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>HHM1776B3 Abavelisi: TDK Corporation Inkcazo: BALUN 880MHZ-960MHZ 50/50 0603 Ikhona evenkileni: Out stock</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

