



TDK Corporation


## HHM1791A1

Inombolo yendawo: HHM1791A1

Umkhqizi / Umshicileli: TDK Corporation

Ingcaciso yeMveliso: BALUN 2.5GHZ-2.7GHZ 50/100 0603

Maxwebhu: [PDF HHM1791A1.pdf](#)

RoHS Imeko:  Ukukhokela mahala / RoHS Ukuthobela

Umkhumbi: ehong Kong

Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungasakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













### Iinkcukacha zeHHM1791A1

INOMBOLO YENDAWO	HHM1791A1
UMENZI	TDK Corporation
INKCAZO	BALUN 2.5GHZ-2.7GHZ 50/100 0603
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	<a href="#">PDF HHM1791A1.pdf</a>
UCHUNGECHUNGE	HHM
UKUBUYISELA UKULAHLEKA (MIN)	10dB
UHLU LWESIGABA	180° ±10°
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	0603 (1608 Metric)
AMANYE AMAGAMA	445-3997-2
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UKUFAKELA UKULAHLEKA (MAX)	0.8dB
UKUNYAMEZELA - UKUNGALINGANI / UKULINGANISELA	50 / 100 Ohm
UHLU LOLWAZI	2.5GHz ~ 2.7GHz
INKCAZO ECACILEYO	RF Balun 2.5GHz ~ 2.7GHz 50 / 100 Ohm 0603 (1608 Metric)

### Amanqaku afanayo

TDK Corporation HHM1791A1	Umhambisi we-HHM1791A1	Umboneleli we-HHM1791A1
Ixabiso le-HHM1791A1	Imifanekiso ye-HHM1791A1	Umfanekiso we-HHM1791A1
Idatha ye-HHM1791A1 yePD	I-HHM1791A1 Khuphela iDatasheet	Idatha ye-HHM1791A1
Ivenkile ye-HHM1791A1	Thenga iHHM1791A1	Thenga iTDK Corporation HHM1791A1
TDK Corporation HHM1791A1	Umboneleli we-TDK Corporation	Umhambisi we-TDK Corporation
TDK Corporation HHM1791A1		

### Iimveliso ezihambelanayo

 <p><b>HHM1904C1</b> Abavelisi: TDK Corporation Inkcazo: BALUN 2.4GHZ-2.5GHZ 50/75 0402 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1903A4</b> Abavelisi: TDK Corporation Inkcazo: BALUN 2.4GHZ-2.5GHZ 50/100 0402 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1763B2</b> Abavelisi: TDK Corporation Inkcazo: BALUN 880MHZ-960MHZ 50/150 0603 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1776B3</b> Abavelisi: TDK Corporation Inkcazo: BALUN 880MHZ-960MHZ 50/50 0603 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1904A1</b> Abavelisi: TDK Corporation Inkcazo: BALUN 2.4GHZ-2.5GHZ 50/75 0402 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1902A1</b> Abavelisi: TDK Corporation Inkcazo: BALUN 2.4GHZ-2.5GHZ 50/50 0402 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1779B1</b> Abavelisi: TDK Corporation Inkcazo: BALUN 2.11-2.17GHZ 50/100 0603 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1903A1</b> Abavelisi: TDK Corporation Inkcazo: BALUN 2.4GHZ-2.5GHZ 50/100 0402 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1752A2</b> Abavelisi: TDK Corporation Inkcazo: BALUN 4.9GHZ-5.95GHZ 50/200 0603 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1775D1</b> Abavelisi: TDK Corporation Inkcazo: BALUN 3.1GHZ-4.9GHZ 50/100 0805 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1776B2</b> Abavelisi: TDK Corporation Inkcazo: BALUN 824MHZ-894MHZ 50/50 0603 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1902B1</b> Abavelisi: TDK Corporation Inkcazo: BALUN 2.4GHZ-2.5GHZ 50/50 0402 Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>