

N/A

DRV5055A2QLPG

Inombolo yendawo:
Umkhiziqi / Umshicileli:
Ingcaciso yeMveliso
Maxwebhu:
Umkhumbi
Indlela yokuthunyelwa

DRV5055A2QLPG
N/A
HALL EFFECT SENSOR

ehong Kong
DHL/Fedex/TNT/UPS/EMS



Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA













Iinkcukacha zeDRV5055A2QLPG

INOMBOLO YENDAWO	DRV5055A2QLPG
UMENZI	N/A
INKCAZO	HALL EFFECT SENSOR
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	3 V ~ 3.63 V, 4.5 V ~ 5.5 V
TE KNOLOJI	Hall Effect
IPHAKHEJI YECANDELO LENKONZO	-
UCHUNGECHUNGE	-
UKWAHLULA	±42mT, ±44mT
ISIGQIBO	-
PACKAGING	Cut Tape (CT)
IPHAKHEJI / IIMEKO	TO-226-3, TO-92-3 (TO-226AA)
UHLOBO LOHLOBO	Analog Voltage
AMANYE AMAGAMA	296-49442 296-49442-1 296-49442-1-ND
UKUSHISA OKUSEBENZAYO	-40°C ~ 125°C (TA)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
IIMBONAKALO	Temperature Compensated
INKCAZO ECACILEYO	Hall Effect Sensor Single Axis
UKUNIKEZELWA KWANGOKU (UMAX)	10mA
I-CURRENT-OUTPUT (MAX)	1mA
BANDWIDTH	20kHz
AXIS	Single

Amanqaku afanayo

DRV5055A2QLPG	Umhambisi we-DRV5055A2QLPG	Umboneleli we-DRV5055A2QLPG
Ixabiso le-DRV5055A2QLPG	Imifanekiso ye-DRV5055A2QLPG	Umfanekiso we-DRV5055A2QLPG
Idatha ye-DRV5055A2QLPG yePD	I-DRV5055A2QLPG Khuphela iDatasheet	Idatha ye-DRV5055A2QLPG
Ivenkile ye-DRV5055A2QLPG	Thenga iDRV5055A2QLPG	Thenga i DRV5055A2QLPG
DRV5055A2QLPG	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

 DRV5055A1QLPG Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 83149 pcs RFQ	 DRV5055A3QLPGM Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 99143 pcs RFQ
 DRV5055A3QDBZT Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 94688 pcs RFQ	 DRV5055A1QDBZT Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 98238 pcs RFQ
 DRV5055A1QDBZR Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 106440 pcs RFQ	 DRV5055A3QDBZR Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 100087 pcs RFQ
 DRV5055A4QDBZR Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 87882 pcs RFQ	 DRV5055A2QDBZR Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 94007 pcs RFQ
 DRV5055A1QLPGM Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 67667 pcs RFQ	 DRV5055A2QLPGM Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 87707 pcs RFQ
 DRV5055A2QDBZT Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 92650 pcs RFQ	 DRV5055A3QLPG Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 64295 pcs RFQ