



AVX Corporation

## CP0603A1880BLTR

Inombolo yendawo: CP0603A1880BLTR

Umkhqizi / Umshicileli: AVX Corporation

Ingcaciso yeMveliso: RF DIR COUPLER 1.85-1.91GHZ 0603

Maxwebhu: [CP0603A1880BLTR.pdf](#)RoHS Imeko:  Iqukethe i-lead / RoHS engahambelaniyo

Umkhumbi: ehong Kong

Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.





### Iinkcukacha zeCP0603A1880BLTR

INOMBOLO YENDAWO	CP0603A1880BLTR
UMENZI	AVX Corporation
INKCAZO	RF DIR COUPLER 1.85-1.91GHZ 0603
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Iqukethe i-lead / RoHS engahambelaniyo
ISHITI YEDATHA	<a href="#">CP0603A1880BLTR.pdf</a>
IPHAKHEJI YECANDELO LENKONZO	0603
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKELWA	25dB
AMANDLA - UMAX	3W
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	0603 (1608 Metric)
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	10 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Contains lead / RoHS non-compliant
ISOLATION	-33dB
UKUFAKELA UKULAHLEKA	0.25dB
UKUPHINDAPHINDA	1.85GHz ~ 1.91GHz
INKCAZO ECACILEYO	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 16.2dB 3W 0603 (1608 Metric)
FACT FACTOR	16.2dB
UHLOBO LODIDI	Standard
IZICELO	PCS

### Amanqaku afanayo

AVX Corporation CP0603A1880BLTR	Umhambisi we-CP0603A1880BLTR	Umboneleli we-CP0603A1880BLTR
Ixabiso le-CP0603A1880BLTR	Imifanekiso ye-CP0603A1880BLTR	Umfanekiso we-CP0603A1880BLTR
Idatha ye-CP0603A1880BLTR yePD	I-CP0603A1880BLTR Khuphela iDatasheet	Idatha ye-CP0603A1880BLTR
Ivenkile ye-CP0603A1880BLTR	Thenga iCP0603A1880BLTR	Thenga iAVX Corporation CP0603A1880BLTR
AVX Corporation CP0603A1880BLTR	Umboneleli we-AVX Corporation	Umhambisi we-AVX Corporation
AVX Corporation CP0603A1880BLTR	AVX Corporation [MIL] CP0603A1880BLTR	

### Iimveliso ezihambelanayo

 <p><b>CP0603A1880ENTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603A1842CWTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.805-1.88GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603A1880DWTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603A1747MLTR\500</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.71-1.785GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603A1880BNTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603A1880ALTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603A1880ELTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603A1880ANTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603A1880HLTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603A1767MNTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.767GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603A1880AWTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603A1880CLTR</b> Abavelisi: AVX Corporation Inkcazo: RF DIR COUPLER 1.85-1.91GHZ 0603 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>

**Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com**

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

