

N/A

CDC2509APWRG4

Inombolo yendawo:

CDC2509APWRG4

Umkhqizi / Umshicileli:

N/A

Ingcaciso yeMveliso

IC 3.3V PLL CLK-DRVR 24-TSSOP

Maxwebhu:

RoHS Imeko

Ukukhokela mahala / RoHS Ukuthobela

Umkhumbi

ehong Kong

Indlela yokuthunyelwa

DHL/Fedex/TNT/UPS/EMS



No Picture

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA

Iinkcukacha zeCDC2509APWRG4

INOMBOLO YENDAWO	CDC2509APWRG4
UMENZI	N/A
INKCAZO	IC 3.3V PLL CLK-DRVR 24-TSSOP
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	3 V ~ 3.6 V
UHLOBO	PLL Clock Driver
IPHAKHEJI YECANDELO LENKONZO	24-TSSOP
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKA: ISIPHUMO	1:9
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	24-TSSOP (0.173", 4.40mm Width)
PLL	Yes with Bypass
ISIPHUMO	LVTTTL
UKUSHISA OKUSEBENZAYO	0°C ~ 70°C
INANI LEESEKETHE	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INPUT	LVTTTL
UKUPHINDAPHINDA - UMAX	100MHz
UHLU LOLUNTU / UMANINZI	No/No
UKWAHLULA - INQAKU: UMPHUMO	No/No
ISIQENDU SENOMBOLO YESISEKO	CDC2509

Amanqaku afanayo

CDC2509APWRG4	Umhambisi we-CDC2509APWRG4	Umboneleli we-CDC2509APWRG4
Ixabiso le-CDC2509APWRG4	Imifanekiso ye-CDC2509APWRG4	Umfanekiso we-CDC2509APWRG4
Idatha ye-CDC2509APWRG4 yePD	I-CDC2509APWRG4 Khuphela iDatasheet	Idatha ye-CDC2509APWRG4
Ivenkile ye-CDC2509APWRG4	Thenga iCDC2509APWRG4	Thenga i CDC2509APWRG4
CDC2509APWRG4	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

<p>CDC2509BPWG4 Abavelisi: N/A Inkcazo: IC PLL CLOCK DVR 3.3V 24-TSSOP Ikhona evenkileni: 5121 pcs</p> <p>RFQ</p>	<p>CDC2509BPW Abavelisi: N/A Inkcazo: IC PLL CLOCK DVR 3.3V 24-TSSOP Ikhona evenkileni: 4346 pcs</p> <p>RFQ</p>
<p>CDC2351QDBG4 Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:10 100MHZ 24SSOP Ikhona evenkileni: 9006 pcs</p> <p>RFQ</p>	<p>CDC2351MDBREP Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:10 100MHZ 24SSOP Ikhona evenkileni: 7312 pcs</p> <p>RFQ</p>
<p>CDC2351QDB Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:10 100MHZ 24SSOP Ikhona evenkileni: 9440 pcs</p> <p>RFQ</p>	<p>CDC2509CPWG4 Abavelisi: N/A Inkcazo: IC 3.3V PLL CLK-DRVR 24-TSSOP Ikhona evenkileni: 10629 pcs</p> <p>RFQ</p>
<p>CDC2509BPWRG4 Abavelisi: N/A Inkcazo: IC 3.3V PLL CLK-DRVR 24-TSSOP Ikhona evenkileni: 30197 pcs</p> <p>RFQ</p>	<p>CDC2351QDBRG4 Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:10 100MHZ 24SSOP Ikhona evenkileni: 11853 pcs</p> <p>RFQ</p>
<p>CDC2351QDBR Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:10 100MHZ 24SSOP Ikhona evenkileni: 12907 pcs</p> <p>RFQ</p>	<p>CDC2509CPW Abavelisi: N/A Inkcazo: IC 3.3V PLL CLK-DRVR 24-TSSOP Ikhona evenkileni: 9772 pcs</p> <p>RFQ</p>
<p>CDC2509APWR Abavelisi: N/A Inkcazo: IC 3.3V PLL CLK-DRVR 24-TSSOP Ikhona evenkileni: 4465 pcs</p> <p>RFQ</p>	<p>CDC2509BPWR Abavelisi: N/A Inkcazo: IC 3.3V PLL CLK-DRVR 24-TSSOP Ikhona evenkileni: 26372 pcs</p> <p>RFQ</p>