

N/A

LMK04011BISQ/NOPB

Inombolo yendawo:	LMK04011BISQ/NOPB
Umkhiziqi / Umshicileli:	N/A
Ingcaciso yeMveliso	IC CLOCK COND W/PLL 48WQFN
Maxwebhu:	
RoHS Imeko	Ukukhokela mahala / RoHS Ukuthobela
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

Inkcukacha zeLMK04011BISQ/NOPB

INOMBOLO YENDAWO	LMK04011BISQ/NOPB
UMENZI	N/A
INKCAZO	IC CLOCK COND W/PLL 48WQFN
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	3.15 V ~ 3.45 V
UHLOBO	Clock Conditioner
IPHAKHEJI YECANDELO LENKONZO	48-WQFN (7x7)
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKA: ISIPHUMO	2:5
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	48-WFQFN Exposed Pad
PLL	Yes
ISIPHUMO	2VPECL, LVPECL
AMANYE AMAGAMA	LMK04011BISQ LMK04011BISQ-ND
UKUSHISA OKUSEBENZAYO	-40°C ~ 85°C
INANI LEESEKETHE	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	3 (168 Hours)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	26 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INPUT	LVC MOS, LVDS, LVPECL
UKUPHINDAPHINDA - UMAX	1.57GHz
UHLU LOLUNTU / UMANINZI	Yes/Yes
UKWAHLULA - INQAKU: UMPHUMO	Yes/Yes
ISIQENDU SENOMBOLO YESISEKO	LMK04011

Amanqaku afanayo

LMK04011BISQ/NOPB	Umhambisi we-LMK04011BISQ/NOPB	Umboneleli we-LMK04011BISQ/NOPB
Ixabiso le-LMK04011BISQ/NOPB	Imifanekiso ye-LMK04011BISQ/NOPB	Umfanekiso we-LMK04011BISQ/NOPB
Idatha ye-LMK04011BISQ/NOPB yePD	I-LMK04011BISQ/NOPB Khuphela iDatasheet	Idatha ye-LMK04011BISQ/NOPB
Ivenkile ye-LMK04011BISQ/NOPB	Thenga iLMK04011BISQ/NOPB	Thenga i LMK04011BISQ/NOPB
LMK04011BISQ/NOPB	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

<p>LMK04031BEVAL/NOPB Abavelisi: N/A Inkcazo: EVAL BOARD LMK04031BISQ Ikhona evenkileni: 337 pcs</p> <p>RFQ</p>	<p>LMK04011BISQX/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND W/PLL 48WQFN Ikhona evenkileni: 7598 pcs</p> <p>RFQ</p>
<p>LMK04010BISQ/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND W/PLL 48WQFN Ikhona evenkileni: 6904 pcs</p> <p>RFQ</p>	<p>LMK04002BISQE/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND 1.6GHZ W/PLL 48QFN Ikhona evenkileni: 5843 pcs</p> <p>RFQ</p>
<p>LMK04002BISQ/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND W/PLL 48WQFN Ikhona evenkileni: 7413 pcs</p> <p>RFQ</p>	<p>LMK04002BISQX/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND W/PLL 48WQFN Ikhona evenkileni: 7620 pcs</p> <p>RFQ</p>
<p>LMK04010BISQX/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND W/PLL 48WQFN Ikhona evenkileni: 6887 pcs</p> <p>RFQ</p>	<p>LMK04031BISQE/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND W/PLL 48WQFN Ikhona evenkileni: 5220 pcs</p> <p>RFQ</p>
<p>LMK04031BEVALXO Abavelisi: N/A Inkcazo: BOARD EVAL PREC CLOCK PLL XO Ikhona evenkileni: 5095 pcs</p> <p>RFQ</p>	<p>LMK04011BISQE/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND W/PLL 48WQFN Ikhona evenkileni: 5033 pcs</p> <p>RFQ</p>
<p>LMK04031BISQ/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND W/PLL 48WQFN Ikhona evenkileni: 7600 pcs</p> <p>RFQ</p>	<p>LMK04010BISQE/NOPB Abavelisi: N/A Inkcazo: IC CLOCK COND 1.2GHZ W/PLL 48QFN Ikhona evenkileni: 5465 pcs</p> <p>RFQ</p>