



Pulse Electronics Corporation

TM1062FCA1

| | |
|-------------------------|--|
| Inombolo yendawo: | TM1062FCA1 |
| Umkhqizi / Umshicileli: | Pulse Electronics Corporation |
| Ingcaciso yeMveliso | TRANSCEIVER PBC |
| Maxwebhu: | 1.TM1062FCA1.pdf 2.TM1062FCA1.pdf |
| RoHS Imeko | Cela ukuqinisekiswa kwempahla / i-RoHS engahambelaniyo |
| Umkhumbi | ehong Kong |
| Indlela yokuthunyelwa | DHL/Fedex/TNT/UPS/EMS |

ISICELO

SESIKATSHULWA

Umfanekiso ungasolwa. Bona iinkcukacha zeenkukacha zeemveliso.

Iinkcukacha zeTM1062FCA1

| | |
|---------------------------------------|--|
| INOMBOLO YENDAWO | TM1062FCA1 |
| UMENZI | Pulse Electronics Corporation |
| INKCAZO | TRANSCEIVER PBC |
| ISIMO SOBUME BENKOKELI / ISIMO SEROHS | Cela ukuqinisekiswa kwempahla / i-RoHS engahambelaniyo |
| ISHITI YEDATHA | 1.TM1062FCA1.pdf 2.TM1062FCA1.pdf |
| UKUNIKEZELA NGEEVOTSI | 5V |
| UHLOBO | Transceiver |
| IPHAKHEJI YECANDELO LENKONZO | Module |
| UCHUNGECHUNGE | Copperhead™ |
| PROTOCOL | IEEE 1394B |
| IPHAKHEJI / IIMEKO | 28-SMD Module |
| UKUSHISA OKUSEBENZAYO | -55°C ~ 125°C |
| INANI LABAQHUBI / ABAFUMANAYO | 1/1 |
| UHLOBO LOKUPHAKAMISA | Surface Mount |
| INQANABA LOKUSONDEZA UBUNINZI (MSL) | 3 (168 Hours) |
| IXESHA LENKQUBO YENKOKELI YEHLABATHI | 19 Weeks |
| ISIMO SOBUME BENKOKELI / ISIMO SEROHS | Request inventory verification / RoHS non-compliant |
| DUPLEX | - |
| INKCAZO ECACILEYO | 1/1 Transceiver IEEE 1394B Module |
| IXABISO LEDATHA | 1.062Gbps |

Amanqaku afanayo

| | | |
|--|---|--|
| Pulse Electronics Corporation TM1062FCA1 | Umhambisi we-TM1062FCA1 | Umboneleli we-TM1062FCA1 |
| Ixabiso le-TM1062FCA1 | Imifanekiso ye-TM1062FCA1 | Umfanekiso we-TM1062FCA1 |
| Idatha ye-TM1062FCA1 yePD | I-TM1062FCA1 Khuphela iDatasheet | Idatha ye-TM1062FCA1 |
| Ivenkile ye-TM1062FCA1 | Thenga iTM1062FCA1 | Thenga iPulse Electronics Corporation TM1062FCA1 |
| Pulse Electronics Corporation TM1062FCA1 | Umboneleli we-Pulse Electronics Corporation | Umhambisi we-Pulse Electronics Corporation |
| Pulse Electronics Corporation TM1062FCA1 | Pulse A Technitrol Company TM1062FCA1 | Pulse TM1062FCA1 |

Iimveliso ezihambelanayo

| | |
|--|--|
| <p>TM1062DUXB Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> | <p>TM1062HSB1 Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER TM1062HSB1 PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
| <p>TM1062DVB2 Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> | <p>TM1062DUB2 Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
| <p>TM1062FUB Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER MODULE PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> | <p>TM1062DVB Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER MODULE PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
| <p>TM1062FSB2 Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER MODULE PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> | <p>TM1062FCA2 Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
| <p>TM1062DUA1 Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> | <p>TM1062DVA1 Abavelisi: Pulse Electronics Corporation Inkcazo: MIL-AERO Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
| <p>TM1062FSB Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER MODULE PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> | <p>TM1062FSA Abavelisi: Pulse Electronics Corporation Inkcazo: TRANSCEIVER PBC Ikhona evenkileni: Out stock</p> <p>RFQ</p> |

