

N/A

CDCV857DGG

Inombolo yendawo:

CDCV857DGG

Umkhiziqi / Umshicileli:

N/A

Ingcaciso yeMveliso

IC SSTL-II PLL CLK-DRVR 48TSSOP

Maxwebhu:

 Ukukhokela mahala / RoHS Ukuthobela

RoHS Imeko

ehong Kong

Umkhumbi

DHL/Fedex/TNT/UPS/EMS

Indlela yokuthunyelwa



No Picture

Umfanekiso ungapheleli. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA













Iinkcukacha zeCDCV857DGG

INOMBOLO YENDAWO	CDCV857DGG
UMENZI	N/A
INKCAZO	IC SSTL-II PLL CLK-DRVR 48TSSOP
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	2.3 V ~ 2.7 V
UHLOBO	PLL Clock Driver
IPHAKHEJI YECANDELO LENKONZO	48-TSSOP
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKA: ISIPHUMO	1:10
PACKAGING	Tube
IPHAKHEJI / IIMEKO	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
ISIPHUMO	Clock
AMANYE AMAGAMA	296-24143-5 CDCV857DGG-ND
UKUSHISA OKUSEBENZAYO	0°C ~ 85°C
INANI LEESEKETHE	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	2 (1 Year)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INPUT	Clock
UKUPHINDAPHINDA - UMAX	200MHz
UHLU LOLUNTU / UMANINZI	No/No
UKWAHLULA - INQAKU: UMPHUMO	Yes/Yes
ISIQENDU SENOMBOLO YESISEKO	CDCV857

Amanqaku afanayo

CDCV857DGG	Umhambisi we-CDCV857DGG	Umboneleli we-CDCV857DGG
Ixabiso le-CDCV857DGG	Imifanekiso ye-CDCV857DGG	Umfanekiso we-CDCV857DGG
Idatha ye-CDCV857DGG yePD	I-CDCV857DGG Khuphela iDatasheet	Idatha ye-CDCV857DGG
Ivenkile ye-CDCV857DGG	Thenga iCDCV857DGG	Thenga i CDCV857DGG
CDCV857DGG	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

 <p>CDCV857DGGRG4 Abavelisi: N/A Inkcazo: IC SSTL-II PLL CLK-DRVR 48TSSOP Ikhona evenkileni: 5405 pcs</p> <p>RFQ</p>	 <p>CDCVF111FNG4 Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:9 650MHZ 28PLCC Ikhona evenkileni: 5389 pcs</p> <p>RFQ</p>
 <p>CDCV857DGGG4 Abavelisi: N/A Inkcazo: IC SSTL-II PLL CLK-DRVR 48TSSOP Ikhona evenkileni: 4677 pcs</p> <p>RFQ</p>	 <p>CDCV857BGQLR Abavelisi: N/A Inkcazo: IC 2.5V PLL CLOCK DRVR 56-BGA Ikhona evenkileni: 4617 pcs</p> <p>RFQ</p>
 <p>CDCV857BIDGGR Abavelisi: N/A Inkcazo: IC SSTL-II PLL CLK-DRVR 48TSSOP Ikhona evenkileni: 16291 pcs</p> <p>RFQ</p>	 <p>CDCV857BDGGRG4 Abavelisi: N/A Inkcazo: IC SSTL-II PLL CLK-DRVR 48TSSOP Ikhona evenkileni: 22822 pcs</p> <p>RFQ</p>
 <p>CDCVF111FNR Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:9 650MHZ 28PLCC Ikhona evenkileni: 7790 pcs</p> <p>RFQ</p>	 <p>CDCV857BIDGGRG4 Abavelisi: N/A Inkcazo: IC SSTL-II PLL CLK-DRVR 48TSSOP Ikhona evenkileni: 19369 pcs</p> <p>RFQ</p>
 <p>CDCV857DGGR Abavelisi: N/A Inkcazo: IC SSTL-II PLL CLK-DRVR 48-TSSOP Ikhona evenkileni: 5363 pcs</p> <p>RFQ</p>	 <p>CDCV857BIDGGG4 Abavelisi: N/A Inkcazo: IC SSTL-II PLL CLK-DRVR 48-TSSOP Ikhona evenkileni: 8726 pcs</p> <p>RFQ</p>
 <p>CDCV857BIDGG Abavelisi: N/A Inkcazo: IC SSTL-II PLL CLK-DRVR 48-TSSOP Ikhona evenkileni: 10910 pcs</p> <p>RFQ</p>	 <p>CDCVF111FN Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:9 650MHZ 28PLCC Ikhona evenkileni: 6603 pcs</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

