

N/A

LMK00304SQX/NOPB

Inombolo yendawo:	LMK00304SQX/NOPB
Umkhiziqi / Umshicileli:	N/A
Ingcaciso yeMveliso	IC CLK BUFFER 3:5 3.1GHZ 32WQFN
Maxwebhu:	
RoHS Imeko	Ukukhokela mahala / RoHS Ukuthobela
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

Iinkcukacha zeLMK00304SQX/NOPB

INOMBOLO YENDAWO	LMK00304SQX/NOPB
UMENZI	N/A
INKCAZO	IC CLK BUFFER 3:5 3.1GHZ 32WQFN
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	3.15 V ~ 3.45 V
UHLOBO	Fanout Buffer (Distribution), Multiplexer, Translator
IPHAKHEJI YECANDELO LENKONZO	32-WQFN (5x5)
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKA: ISIPHUMO	3:5
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	32-WFQFN Exposed Pad
ISIPHUMO	HCSL, LVCMOS, LVDS, LVPECL
UKUSHISA OKUSEBENZAYO	-40°C ~ 85°C
INANI LEESEKETHE	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	3 (168 Hours)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INPUT	CML, HCSL, HSTL, LVDS, LVPECL, SSTL, Crystal
UKUPHINDAPHINDA - UMAX	3.1GHz
UKWAHLULA - INQAKU: UMPHUMO	Yes/Yes
INKCAZO ECACILEYO	Clock Fanout Buffer (Distribution), Multiplexer, Translator IC 3:5 3.1GHz 32-WFQFN Exposed Pad
ISIQENDU SENOMBOLO YESISEKO	LMK00304

Amanqaku afanayo

LMK00304SQX/NOPB	Umhambisi we-LMK00304SQX/NOPB	Umboneleli we-LMK00304SQX/NOPB
Ixabiso le-LMK00304SQX/NOPB	Imifanekiso ye-LMK00304SQX/NOPB	Umfanekiso we-LMK00304SQX/NOPB
Idatha ye-LMK00304SQX/NOPB yePD	I-LMK00304SQX/NOPB Khuphela iDatasheet	Idatha ye-LMK00304SQX/NOPB
Ivenkile ye-LMK00304SQX/NOPB	Thenga iLMK00304SQX/NOPB	Thenga i LMK00304SQX/NOPB
LMK00304SQX/NOPB	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

<p>LMK00306SQ/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Ikhona evenkileni: 15141 pcs</p> <p>RFQ</p>	<p>LMK00301SQ/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Ikhona evenkileni: 16276 pcs</p> <p>RFQ</p>
<p>LMK00306SQE/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Ikhona evenkileni: 15164 pcs</p> <p>RFQ</p>	<p>LMK00308SQ/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:9 3.1GHZ 40WQFN Ikhona evenkileni: 16225 pcs</p> <p>RFQ</p>
<p>LMK00308EVM/NOPB Abavelisi: N/A Inkcazo: BOARD EVAL FOR LMK00308 Ikhona evenkileni: 337 pcs</p> <p>RFQ</p>	<p>LMK00304SQ/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:5 3.1GHZ 32WQFN Ikhona evenkileni: 24218 pcs</p> <p>RFQ</p>
<p>LMK00304SQE/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:5 3.1GHZ 32WQFN Ikhona evenkileni: 16840 pcs</p> <p>RFQ</p>	<p>LMK00306EVM/NOPB Abavelisi: N/A Inkcazo: BOARD EVAL FOR LMK00306 Ikhona evenkileni: 409 pcs</p> <p>RFQ</p>
<p>LMK00301SQX/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Ikhona evenkileni: 17670 pcs</p> <p>RFQ</p>	<p>LMK00304EVM/NOPB Abavelisi: N/A Inkcazo: BOARD EVAL FOR LMK00304 Ikhona evenkileni: 425 pcs</p> <p>RFQ</p>
<p>LMK00301SQE/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Ikhona evenkileni: 10236 pcs</p> <p>RFQ</p>	<p>LMK00306SQX/NOPB Abavelisi: N/A Inkcazo: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Ikhona evenkileni: 19578 pcs</p> <p>RFQ</p>