

N/A

CDCV850DGGRG4

Inombolo yendawo:

CDCV850DGGRG4

Umkhqizi / Umshicileli:

N/A

Ingcaciso yeMveliso

IC PLL CLOCK DRVR 2.5V 48TSSOP

Maxwebhu:

RoHS Imeko

 Ukukhokela mahala / RoHS Ukuthobela

Umkhumbi

ehong Kong

Indlela yokuthunyelwa

DHL/Fedex/TNT/UPS/EMS



No Picture

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA













Iinkcukacha zeCDCV850DGGRG4

INOMBOLO YENDAWO	CDCV850DGGRG4
UMENZI	N/A
INKCAZO	IC PLL CLOCK DRVR 2.5V 48TSSOP
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	2.3 V ~ 2.7 V
UHLOBO	PLL Clock Driver
IPHAKHEJI YECANDELO LENKONZO	48-TSSOP
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKA: ISIPHUMO	1:11
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
ISIPHUMO	SSTL-2
UKUSHISA OKUSEBENZAYO	0°C ~ 85°C
INANI LEESEKETHE	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	2 (1 Year)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INPUT	LVTTTL, SSTL-2
UKUPHINDAPHINDA - UMAX	140MHz
UHLU LOLUNTU / UMANINZI	No/No
UKWAHLULA - INQAKU: UMPHUMO	Yes/Yes
ISIQENDU SENOMBOLO YESISEKO	CDCV850

Amanqaku afanayo

CDCV850DGGRG4	Umhambisi we-CDCV850DGGRG4	Umboneleli we-CDCV850DGGRG4
Ixabiso le-CDCV850DGGRG4	Imifanekiso ye-CDCV850DGGRG4	Umfanekiso we-CDCV850DGGRG4
Idatha ye-CDCV850DGGRG4 yePD	I-CDCV850DGGRG4 Khuphela iDatasheet	Idatha ye-CDCV850DGGRG4
Ivenkile ye-CDCV850DGGRG4	Thenga iCDCV850DGGRG4	Thenga i CDCV850DGGRG4
CDCV850DGGRG4	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

 <p>CDCV850DGGR Abavelisi: N/A Inkcazo: IC PLL CLOCK DRVR 2.5V 48-TSSOP Ikhona evenkileni: 26517 pcs</p> <p>RFQ</p>	 <p>CDCV304TPWREP Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:4 200MHZ 8TSSOP Ikhona evenkileni: 21714 pcs</p> <p>RFQ</p>
 <p>CDCV304PWR Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:4 200MHZ 8TSSOP Ikhona evenkileni: 53713 pcs</p> <p>RFQ</p>	 <p>CDCV850IDGGG4 Abavelisi: N/A Inkcazo: IC PLL CLOCK DRVR 2.5V 48TSSOP Ikhona evenkileni: 14095 pcs</p> <p>RFQ</p>
 <p>CDCV850IDGG Abavelisi: N/A Inkcazo: IC PLL CLOCK DRVR 2.5V 48-TSSOP Ikhona evenkileni: 23791 pcs</p> <p>RFQ</p>	 <p>CDCV850IDGGR Abavelisi: N/A Inkcazo: IC PLL CLOCK DRVR 2.5V 48TSSOP Ikhona evenkileni: 4418 pcs</p> <p>RFQ</p>
 <p>CDCV850DGGG4 Abavelisi: N/A Inkcazo: IC PLL CLOCK DRVR 2.5V 48TSSOP Ikhona evenkileni: 19469 pcs</p> <p>RFQ</p>	 <p>CDCV850IDGGRG4 Abavelisi: N/A Inkcazo: IC PLL CLOCK DRVR 2.5V 48TSSOP Ikhona evenkileni: 4037 pcs</p> <p>RFQ</p>
 <p>CDCV304PWRG4 Abavelisi: N/A Inkcazo: IC CLK BUFFER 1:4 200MHZ 8TSSOP Ikhona evenkileni: 66794 pcs</p> <p>RFQ</p>	 <p>CDCV855IPW Abavelisi: N/A Inkcazo: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Ikhona evenkileni: 38134 pcs</p> <p>RFQ</p>
 <p>CDCV850DGG Abavelisi: N/A Inkcazo: IC PLL CLOCK DRVR 2.5V 48-TSSOP Ikhona evenkileni: 22414 pcs</p> <p>RFQ</p>	 <p>CDCV855IPWG4 Abavelisi: N/A Inkcazo: IC PLL CLOCK DRVR 2.5V 28TSSOP Ikhona evenkileni: 26506 pcs</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

