



ADI (Analog Devices, Inc.)

AD8364ACPZ-REEL7

Inombolo yendawo: AD8364ACPZ-REEL7

Umkhiziqi / Umshicileli: ADI (Analog Devices, Inc.)

Ingcaciso yeMveliso: IC RF DETECT 2.7GHZ 32LFCSP

Maxwebhu: [PDF AD8364ACPZ-REEL7.pdf](#)RoHS Imeko:  Ukukhokela mahala / RoHS Ukuthobela

Umkhumbi: ehong Kong

Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

Iinkcukacha zeAD8364ACPZ-REEL7

INOMBOLO YENDAWO	AD8364ACPZ-REEL7
UMENZI	ADI (Analog Devices, Inc.)
INKCAZO	IC RF DETECT 2.7GHZ 32LFCSP
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	PDF AD8364ACPZ-REEL7.pdf
UKUNIKEZELA NGEEVOTSI	4.5 V ~ 5.5 V
IPHAKHEJI YECANDELO LENKONZO	32-LFCSP-VQ (5x5)
UCHUNGECHUNGE	-
UHLOBO LWERF	Cellular, CDMA
PACKAGING	Original-Reel®
IPHAKHEJI / IIMEKO	32-VFQFN Exposed Pad, CSP
AMANYE AMAGAMA	AD8364ACPZ-REEL7DKR
INQANABA LOKUSONDEZA UBUNINZI (MSL)	3 (168 Hours)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	21 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UHLOBO LOKUFAKA	-55dBm ~ 5dBm
UKUPHINDAPHINDA	2.7GHz
INKCAZO ECACILEYO	RF Detector IC Cellular, CDMA 2.7GHz -55dBm ~ 5dBm ±0.5dB 32-VFQFN Exposed Pad, CSP
UKUNIKEZELWA KWANGOKU	70mA
ISIQENDU SENOMBOLO YESISEKO	AD8364
UKUCHANEKA	±0.5dB

Amanqaku afanayo

ADI (Analog Devices, Inc.) AD8364ACPZ-REEL7	Umhambisi we-AD8364ACPZ-REEL7	Umboneleli we-AD8364ACPZ-REEL7
Ixabiso le-AD8364ACPZ-REEL7	Imifanekiso ye-AD8364ACPZ-REEL7	Umfanekiso we-AD8364ACPZ-REEL7
Idatha ye-AD8364ACPZ-REEL7 yePD	I-AD8364ACPZ-REEL7 Khuphela iDatasheet	Idatha ye-AD8364ACPZ-REEL7
Ivenkile ye-AD8364ACPZ-REEL7	Thenga iAD8364ACPZ-REEL7	Thenga iADI (Analog Devices, Inc.) AD8364ACPZ-REEL7
ADI (Analog Devices, Inc.) AD8364ACPZ-REEL7	Umboneleli we-ADI (Analog Devices, Inc.)	Umhambisi we-ADI (Analog Devices, Inc.)
ADI (Analog Devices, Inc.) AD8364ACPZ-REEL7	AD AD8364ACPZ-REEL7	ADI (Analog Devices, Inc.) AD8364ACPZ-REEL7
Analog Devices Inc. AD8364ACPZ-REEL7	Analog Devices, Inc. AD8364ACPZ-REEL7	

Iimveliso ezihambelanayo

 <p>AD8366-EVALZ Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: EVAL BOARD FOR AD8366 Ikhona evenkileni: 2 pcs</p> <p>RFQ</p>	 <p>AD8363ACPZ-R7 Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: IC RF DETECT 50HZ-6GHZ 16LFCSP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>AD8367ARU-REEL7 Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: IC OPAMP VGA 500MHZ 14TSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>AD8362ARUZ-REEL7 Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: IC RF DETECT 50HZ-3.8GHZ 16TSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>AD8362ARUZ Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: IC RF DETECT 50HZ-3.8GHZ 16TSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>AD8367ARU Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: IC OPAMP VGA 500MHZ 14TSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>AD8364-EVALZ Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: EVAL BOARD FOR AD8364 Ikhona evenkileni: 2 pcs</p> <p>RFQ</p>	 <p>AD8367ARUZ Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: IC OPAMP VGA 500MHZ 14TSSOP Ikhona evenkileni: 380 pcs</p> <p>RFQ</p>
 <p>AD8363-EVALZ Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: EVAL SYSTEM FOR AD8363 Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>AD8362ARU Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: IC RF DETECT 50HZ-3.8GHZ 16TSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
 <p>AD8366ACPZ-R7 Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: IC OPAMP VGA 600MHZ 32LFCSP Ikhona evenkileni: Out stock</p> <p>RFQ</p>	 <p>AD8367-EVALZ Abavelisi: ADI (Analog Devices, Inc.) Inkcazo: BOARD EVALUATION FOR AD8367 Ikhona evenkileni: 1 pcs</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

