

**RENESAS**

Renesas Electronics America

## HD6473827RHV

Inombolo yendawo:

HD6473827RHV

Umkhiziqi / Umshicileli:

Renesas Electronics America

Ingcaciso yeMveliso

IC MCU 8BIT 60KB OTP 80QFP

Maxwebhu:

 HD6473827RHV.pdf

RoHS Imeko

 Ukukhokela mahala / RoHS Ukuthobela

Umkhumbi

ehong Kong

Indlela yokuthunyelwa


DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













### Iinkcukacha zeHD6473827RHV

INOMBOLO YENDAWO	HD6473827RHV
UMENZI	Renesas Electronics America
INKCAZO	IC MCU 8BIT 60KB OTP 80QFP
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	 HD6473827RHV.pdf
I-VOLTAGE - SUPPLY (VCC / VDD)	1.8 V ~ 5.5 V
IPHAKHEJI YECANDELO LENKONZO	80-QFP (14x14)
UKUKHAWULEZA	8MHz
UCHUNGECHUNGE	H8@ H8/300L SLP
I-RAM SIZE	2K x 8
UHLOBO LWEMEMORI	OTP
SIZE IMEMORI	60KB (60K x 8)
IIPHERIPHERALS	LCD, PWM, WDT
PACKAGING	Tray
IPHAKHEJI / IIMEKO	80-BQFP
UHLOBO LWE-OSCILLATOR	Internal
UKUSHISA OKUSEBENZAYO	-20°C ~ 75°C (TA)
INANI LE-I / O	55
INQANABA LOKUSONDEZA UBUNINZI (MSL)	3 (168 Hours)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UHLOBO LWEEEPROM	-
INKCAZO ECACILEYO	H8/300L H8@ H8/300L SLP Microcontroller IC 8-Bit 8MHz 60KB (60K x 8) OTP 80-QFP (14x14)
ABAGUQULELI BEDATHA	A/D 8x10b
UBUNGAKANANI BEMPAHLA	8-Bit
INKQUBO YOMSEBENZI	H8/300L
UKUDIBANISA	SCI
ISIQENDU SENOMBOLO YESISEKO	HD6473827

### Amanqaku afanayo

Renesas Electronics America HD6473827RHV	Umhambisi we-HD6473827RHV	Umboneleli we-HD6473827RHV
Ixabiso le-HD6473827RHV	Imifanekiso ye-HD6473827RHV	Umfanekiso we-HD6473827RHV
Idatha ye-HD6473827RHV yePD	I-HD6473827RHV Khuphela iDatasheet	Idatha ye-HD6473827RHV
Ivenkile ye-HD6473827RHV	Thenga iHD6473827RHV	Thenga iRenesas Electronics America HD6473827RHV
Renesas Electronics America HD6473827RHV	Umboneleli we-Renesas Electronics America	Umhambisi we-Renesas Electronics America
Renesas Electronics America HD6473827RHV	Renesas Technology Corp HD6473827RHV	Renesas HD6473827RHV

### Iimveliso ezihambelanayo

 <p><b>HD6473827RDV</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HD64738024WV</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 8BIT 32KB OTP 80TQFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HD6473802FPV</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 8BIT 16KB OTP 64LQFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HD6473802HV</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 8BIT 16KB OTP 64QFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HD6477042AF28V</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 32BIT 128KB OTP 112QFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HD6473827HV</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HD6473827RWV</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 8BIT 60KB OTP 80TQFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HD64F2378RVFQ34V</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 16BIT 512KB FLASH 144LQFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HD6473867DV</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HD64F3334YFLH16V</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 8BIT 32KB FLASH 80QFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HD64738024WIV</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 8BIT 32KB OTP 80TQFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HD64F3337SF16V</b> Abavelisi: Renesas Electronics America Inkcazo: IC MCU 8BIT 60KB FLASH 80QFP Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>