

N/A

DRV5055A1QLPG

Inombolo yendawo:
 Umkhiqizi / Umshicileli:
 Ingcaciso yeMveliso
 Maxwebhu:
 Umkhumbi
 Indlela yokuthunyelwa

DRV5055A1QLPG
 N/A
 HALL EFFECT SENSOR

 ehong Kong
 DHL/Fedex/TNT/UPS/EMS



Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA

Iinkcukacha zeDRV5055A1QLPG

INOMBOLO YENDAWO	DRV5055A1QLPG
UMENZI	N/A
INKCAZO	HALL EFFECT SENSOR
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	3 V ~ 3.63 V, 4.5 V ~ 5.5 V
TE KNOLOJI	Hall Effect
IPHAKHEJI YECANDELO LENKONZO	-
UCHUNGECHUNGE	-
UKWAHLULA	±21mT, ±22mT
ISIGQIBO	-
PACKAGING	Cut Tape (CT)
IPHAKHEJI / IIMEKO	TO-226-3, TO-92-3 (TO-226AA)
UHLOBO LOHLOBO	Analog Voltage
AMANYE AMAGAMA	296-49441-1 296-49441-1-ND
UKUSHISA OKUSEBENZAYO	-40°C ~ 125°C (TA)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
IIMBONAKALO	Temperature Compensated
INKCAZO ECACILEYO	Hall Effect Sensor Single Axis
UKUNIKEZELWA KWANGOKU (UMAX)	10mA
I-CURRENT-OUTPUT (MAX)	1mA
BANDWIDTH	20kHz
AXIS	Single

Amanqaku afanayo

DRV5055A1QLPG	Umhambisi we-DRV5055A1QLPG	Umboneleli we-DRV5055A1QLPG
Ixabiso le-DRV5055A1QLPG	Imifanekiso ye-DRV5055A1QLPG	Umfanekiso we-DRV5055A1QLPG
Idatha ye-DRV5055A1QLPG yePD	I-DRV5055A1QLPG Khuphela iDatashet	Idatha ye-DRV5055A1QLPG
Ivenkile ye-DRV5055A1QLPG	Thenga iDRV5055A1QLPG	Thenga i DRV5055A1QLPG
DRV5055A1QLPG	Umboneleli we-	Umhambisi we-

Iimveliso ezihambelanayo

<p>DRV5055A1QLPGM Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 67667 pcs</p> <p>RFQ</p>	<p>DRV5055A2QDBZT Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 92650 pcs</p> <p>RFQ</p>
<p>DRV5053VAQLPGMQ1 Abavelisi: N/A Inkcazo: SENSOR LINEAR ANALOG TO92-3 Ikhona evenkileni: 128468 pcs</p> <p>RFQ</p>	<p>DRV5053VAQLPG Abavelisi: N/A Inkcazo: SENSOR LINEAR ANALOG TO92-3 Ikhona evenkileni: 118307 pcs</p> <p>RFQ</p>
<p>DRV5055A3QDBZR Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 100087 pcs</p> <p>RFQ</p>	<p>DRV5055A1QDBZT Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 98238 pcs</p> <p>RFQ</p>
<p>DRV5053VAQLPGQ1 Abavelisi: N/A Inkcazo: SENSOR LINEAR ANALOG TO92-3 Ikhona evenkileni: 83335 pcs</p> <p>RFQ</p>	<p>DRV5055A2QLPGM Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 87707 pcs</p> <p>RFQ</p>
<p>DRV5055A1QDBZR Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 106440 pcs</p> <p>RFQ</p>	<p>DRV5053VAQLPGM Abavelisi: N/A Inkcazo: SENSOR LINEAR ANALOG TO92-3 Ikhona evenkileni: 163744 pcs</p> <p>RFQ</p>
<p>DRV5055A2QDBZR Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 94007 pcs</p> <p>RFQ</p>	<p>DRV5055A2QLPG Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 75526 pcs</p> <p>RFQ</p>