


**71MB36-02-1-04N**

Inombolo yendawo:
 Umkhiziqi / Umshicileli:
 Ingcaciso yeMveliso
 Maxwebhu:
 RoHS Imeko
 Umkhumbi
 Indlela yokuthunyelwa

71MB36-02-1-04N
 Grayhill, Inc.
 SWITCH ROTARY
 I-RoHS Iyavumelana
 ehong Kong
 DHL/Fedex/TNT/UPS/EMS

ISICELO
 SESICATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha ze71MB36-02-1-04N

| | |
|---------------------------------------|--|
| INOMBOLO YENDAWO | 71MB36-02-1-04N |
| UMENZI | Grayhill, Inc. |
| INKCAZO | SWITCH ROTARY |
| ISIMO SOBUME BENKOKELI / ISIMO SEROHS | I-RoHS Iyavumelana |
| ISHITI YEDATHA | |
| I-VOLTAGE RATING - DC | 30V |
| I-VOLTAGE RATING - AC | 115V |
| STYLE TERMINATION | Solder Lug |
| UCHUNGECHUNGE | 71 |
| ISIMO SEROHS | RoHS Compliant |
| I-PANEL CUTOOUT UBUKHULU | - |
| KU SEBENZA | 2.880 ~ 23gfm |
| INANI LEZITHUBA | 4 |
| INANI LEPOLISI NGANYE KWIDECK | 1 |
| INANI LEEDEKS | 2 |
| UHLOBO LOKUPHAKAMISA | Panel Mount |
| INDEX IYAYEKA | Fixed |
| IIMBONAKALO | - |
| INKCAZO ECACILEYO | Rotary Switch 4 Position SP4T 250mA (AC/DC) 115VAC Panel Mount |
| UBUNZULU BEPHANELI | 27.87mm |
| ISILINGANISO SAMANJE | 250mA (AC/DC) |
| QHAGAMSHELANA NEXESHA | Non-Shorting (BBM) |
| IINKCUKACHA ZOQHAGAMSHELWANO | Silver Alloy |
| QHA GA MSHELANA | - |
| ISIPHALUKA NGEDISK | SP4T |
| I-ANGLE OF CAST | 36° |
| UHLOBO LWE-ACTUATOR | Round (4mm Dia) |
| UBUDE BOKUGUQULA | 17.00mm |

Amanqaku afanayo

| | | |
|--------------------------------|---------------------------------------|--|
| Grayhill, Inc. 71MB36-02-1-04N | Umhambisi we-71MB36-02-1-04N | Umboneleli we-71MB36-02-1-04N |
| Ixabiso le-71MB36-02-1-04N | Imifanekiso ye-71MB36-02-1-04N | Umfanekiso we-71MB36-02-1-04N |
| Idatha ye-71MB36-02-1-04N yePD | I-71MB36-02-1-04N Khuphela iDatasheet | Idatha ye-71MB36-02-1-04N |
| Ivenkile ye-71MB36-02-1-04N | Thenga i71MB36-02-1-04N | Thenga iGrayhill, Inc. 71MB36-02-1-04N |
| Grayhill, Inc. 71MB36-02-1-04N | Umboneleli we-Grayhill, Inc. | Umhambisi we-Grayhill, Inc. |
| Grayhill, Inc. 71MB36-02-1-04N | Grayhill Inc. 71MB36-02-1-04N | |

Iimveliso ezihambelanayo

| | |
|--|---|
|  <p>71MB36-02-1-05S Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>71MB36-02-2-03S Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>71MB36-02-1-07N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>71MB36-02-1-05N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>71MB36-01-2-03N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>71MB36-01-2-05S Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>71MB36-01B10N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>71MB36-02-2-03N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>71MB36-02-2-05N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>71MB36-01-2-05N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |
|  <p>71MB36-01-2-02N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |  <p>71MB36-01-2-04N Abavelisi: Grayhill, Inc. Inkcazo: SWITCH ROTARY Ikhona evenkileni: Out stock</p> <p>RFQ</p> |