



NXP Semiconductors / Freescale

UJA1061TW/3V3/C/T/

Inombolo yendawo:	UJA1061TW/3V3/C/T/
Umkhiziqizi / Umshicileli:	NXP Semiconductors / Freescale
Ingcaciso yeMveliso	IC CAN/LIN FAIL-SAFE HS 32HTSSOP
Maxwebhu:	PDF UJA1061TW/3V3/C/T/.pdf
RoHS Imeko	Ukukhokela mahala / RoHS Ukuthobela
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

Inkcukacha zeUJA1061TW/3V3/C/T/

INOMBOLO YENDAWO	UJA1061TW/3V3/C/T/
UMENZI	NXP Semiconductors / Freescale
INKCAZO	IC CAN/LIN FAIL-SAFE HS 32HTSSOP
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	PDF UJA1061TW/3V3/C/T/.pdf
UKUNIKEZELA NGEEVOTSI	5.5 V ~ 27 V
IPHAKHEJI YECANDELO LENKONZO	32-HTSSOP
UCHUNGECHUNGE	-
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	32-TSSOP (0.240", 6.10mm Width) Exposed Pad
AMANYE AMAGAMA	935288865518
UHLORO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	3 (168 Hours)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INTERFACE	CAN, LIN
INKCAZO ECACILEYO	Automotive Networking Interface 32-HTSSOP
ISIQENDU SENOMBOLO YESISEKO	UJA1061
IZICELO	Automotive Networking

Amanqaku afanayo

NXP Semiconductors / Freescale UJA1061TW/3V3/C/T/	Umhambisi we-UJA1061TW/3V3/C/T/	Umboneleli we-UJA1061TW/3V3/C/T/
Ixabiso le-UJA1061TW/3V3/C/T/	Imifanekiso ye-UJA1061TW/3V3/C/T/	Umfanekiso we-UJA1061TW/3V3/C/T/
Idatha ye-UJA1061TW/3V3/C/T/ yePD	I-UJA1061TW/3V3/C/T/ Khuphela iDatasheet	Idatha ye-UJA1061TW/3V3/C/T/
Ivenkile ye-UJA1061TW/3V3/C/T/	Thenga iUJA1061TW/3V3/C/T/	Thenga iNXP Semiconductors / Freescale UJA1061TW/3V3/C/T/
NXP Semiconductors / Freescale UJA1061TW/3V3/C/T/	Umboneleli we-NXP Semiconductors / Freescale	Umhambisi we-NXP Semiconductors / Freescale
NXP Semiconductors / Freescale UJA1061TW/3V3/C/T/	NXP Semiconductors UJA1061TW/3V3/C/T/	Freescale UJA1061TW/3V3/C/T/
Freescale Semiconductor - NXP UJA1061TW/3V3/C/T/	NXP USA Inc. UJA1061TW/3V3/C/T/	

Iimveliso ezihambelanayo

<p>UJA1023T/2R04/C;51 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN I/O SLAVE 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>UJA1061TW/3V3/C/T, Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN FAIL-SAFE HS 32HTSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>UJA1023T/2R04,518 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN I/O SLAVE 16SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>UJA1018TK,118 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC TRANSCEIVER LIN 16HVSON Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>UJA1065TW/3V3,512 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN FAIL-SAFE 32HTSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>UJA1065TW/3V0,518 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN FAIL-SAFE 32HTSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>UJA1023T/2R04/C,51 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN I/O SLAVE 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>UJA1061TW/5V0/C/T, Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN FAIL-SAFE HS 32HTSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>UJA1023T/2R04,512 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN I/O SLAVE 16SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>UJA1061TW/5V0/C/T/ Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN FAIL-SAFE HS 32HTSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>UJA1065TW/3V3,518 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN FAIL-SAFE 32HTSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>UJA1065TW/3V0,512 Abavelisi: NXP Semiconductors / Freescale Inkcazo: IC CAN/LIN FAIL-SAFE 32HTSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>

