



TAIYO YUDEN Taiyo Yuden



FI168T155021-T

Inombolo yendawo: FI168T155021-T
 Umkhiziqi / Umshicileli: Taiyo Yuden
 Ingcaciso yeMveliso: BALUN 900MHZ-2.2GHZ 50/75 0603
 Maxwebhu: [FI168T155021-T.pdf](#)
 RoHS Imeko:  Ukukhokela mahala / RoHS Ukuthobela
 Umkhumbi: ehong Kong
 Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

ISICELO
SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha zeFI168T155021-T

INOMBOLO YENDAWO	FI168T155021-T
UMENZI	Taiyo Yuden
INKCAZO	BALUN 900MHZ-2.2GHZ 50/75 0603
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	FI168T155021-T.pdf
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKA (MIN)	8dB
UHLU LWESIGABA	180° ±20°
PACKAGING	Cut Tape (CT)
IPHAKHEJI / IIMEKO	0603 (1608 Metric)
AMANYE AMAGAMA	587-3256-1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UKUFAKELA UKULAHLEKA (MAX)	2.3dB
UKUNYAMEZELA - UKUNGALINGANI / UKULINGANISELA	50 / 75 Ohm
UHLU LOLWAZI	900MHz ~ 2.2GHz
INKCAZO ECACILEYO	RF Balun 900MHz ~ 2.2GHz 50 / 75 Ohm 0603 (1608 Metric)

Amanqaku afanayo

Taiyo Yuden FI168T155021-T	Umhambisi we-FI168T155021-T	Umboneleli we-FI168T155021-T
Ixabiso le-FI168T155021-T	Imifanekiso ye-FI168T155021-T	Umfanekiso we-FI168T155021-T
Idatha ye-FI168T155021-T yePD	I-FI168T155021-T Khuphela iDatasheet	Idatha ye-FI168T155021-T
Ivenkile ye-FI168T155021-T	Thenga iFI168T155021-T	Thenga iTaiyo Yuden FI168T155021-T
Taiyo Yuden FI168T155021-T	Umboneleli we-Taiyo Yuden	Umhambisi we-Taiyo Yuden
Taiyo Yuden FI168T155021-T		

Iimveliso ezihambelanayo

 <p>FI168P157519-T Abavelisi: Taiyo Yuden Inkcazo: RF DIPLEXER 892MHZ/1.584GHZ 0603 Ikhona evenkileni: Out stock RFQ</p>	 <p>FI168P157525-T Abavelisi: Taiyo Yuden Inkcazo: RF DIPLEXER 892MHZ/1.584GHZ 0603 Ikhona evenkileni: Out stock RFQ</p>
 <p>FI1B002PD Abavelisi: Belden Inkcazo: BO2.5 2F OM1 OFNP TB Ikhona evenkileni: Out stock RFQ</p>	 <p>FI168W1697B1-T Abavelisi: Taiyo Yuden Inkcazo: FILTER, COUPLER, W-CDMA/CDMA/GSM Ikhona evenkileni: Out stock RFQ</p>
 <p>FI168P245010-T Abavelisi: Taiyo Yuden Inkcazo: RF DIPLEXER 2.45GHZ/5.51GHZ 0603 Ikhona evenkileni: Out stock RFQ</p>	 <p>FI168P245014-T Abavelisi: Taiyo Yuden Inkcazo: RF DIPLEXER 0603 6 PC PAD Ikhona evenkileni: Out stock RFQ</p>
 <p>FI168P245030-T Abavelisi: Taiyo Yuden Inkcazo: RF DIPLEXER 1.584/5.425GHZ 0603 Ikhona evenkileni: Out stock RFQ</p>	 <p>FI1B002PB Abavelisi: Belden Inkcazo: FI BO OM1 2F OFNP Ikhona evenkileni: Out stock RFQ</p>
 <p>FI1B002RB Abavelisi: Belden Inkcazo: FI BO OM1 2F OFNR Ikhona evenkileni: Out stock RFQ</p>	 <p>FI168T578717-T Abavelisi: Taiyo Yuden Inkcazo: BALUN 5.725-5.85GHZ 50/100 0603 Ikhona evenkileni: Out stock RFQ</p>
 <p>FI168P245023-T Abavelisi: Taiyo Yuden Inkcazo: RF DIPLEXER 0603 6 PC PAD Ikhona evenkileni: Out stock RFQ</p>	 <p>FI1B004PB Abavelisi: Belden Inkcazo: FI BO OM1 4F OFNP Ikhona evenkileni: Out stock RFQ</p>