



TDK Corporation

## HHM1517

Inombolo yendawo:  
 Umkhqizi / Umshicileli:  
 Ingcaciso yeMveliso  
 Maxwebhu:  
 RoHS Imeko  
 Umkhumbi  
 Indlela yokuthunyelwa


HHM1517  
 TDK Corporation  
 BALUN 2.4GHZ-2.5GHZ 50/50 0805  
 HHM1517.pdf  
 Ukukhokela mahala / RoHS Ukuthobela  
 ehong Kong  
 DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungunakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













### Iinkcukacha zeHHM1517

INOMBOLO YENDAWO	HHM1517
UMENZI	TDK Corporation
INKCAZO	BALUN 2.4GHZ-2.5GHZ 50/50 0805
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	 HHM1517.pdf
UCHUNGECHUNGE	HHM
UKUBUYISELA UKULAHLEKA (MIN)	10dB
UHLU LWESIGABA	180° ±10°
PACKAGING	Tape & Reel (TR)
IPHAKHEJI / IIMEKO	0805 (2012 Metric)
AMANYE AMAGAMA	445-1233-2
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UKUFAKELA UKULAHLEKA (MAX)	1.2dB
UKUNYAMEZELA - UKUNGALINGANI / UKULINGANISELA	50 / 50 Ohm
UHLU LOLWAZI	2.4GHz ~ 2.5GHz
INKCAZO ECACILEYO	RF Balun 2.4GHz ~ 2.5GHz 50 / 50 Ohm 0805 (2012 Metric)

### Amanqaku afanayo

TDK Corporation HHM1517	Umhambisi we-HHM1517	Umboneleli we-HHM1517
Ixabiso le-HHM1517	Imifanekiso ye-HHM1517	Umfanekiso we-HHM1517
Idatha ye-HHM1517 yePD	I-HHM1517 Khuphela iDatasheet	Idatha ye-HHM1517
Ivenkile ye-HHM1517	Thenga iHHM1517	Thenga iTDK Corporation HHM1517
TDK Corporation HHM1517	Umboneleli we-TDK Corporation	Umhambisi we-TDK Corporation
TDK Corporation HHM1517		

### Iimveliso ezihambelanayo

 <p><b>HHM-CU</b>                  Abavelisi: Bussmann (Eaton)                  Inkcazo: FUSE HOLDR BLADE 32V 24A IN LINE                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1517A2</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 2.3GHZ-2.5GHZ 50/50 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1521</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 2.4GHZ-2.5GHZ 50/200 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1506</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN DUAL 50/100 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1522A7</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 824MHZ-894MHZ 50/50 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1515B2</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 880MHZ-960MHZ 50/200 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1520</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 2.4GHZ-2.5GHZ 50/100 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1516</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 1.71-1.99GHZ 50/200 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM15112A1</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 900MHZ-2.2GHZ 75/100 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1520A2</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 2.3GHZ-2.5GHZ 50/100 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1518A3</b>                  Abavelisi: TDK Corporation                  Inkcazo: BALUN 1.71-1.99GHZ 50/150 0805                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM-BLUE</b>                  Abavelisi: Bussmann (Eaton)                  Inkcazo: FUSE HOLDR BLADE 32V 24A IN LINE                  Ikhona evenkileni: Out stock</p> <p><b>RFQ</b></p>