


**25BSF22-B-1-16F**

Inombolo yendawo:	25BSF22-B-1-16F
Umkhqizi / Umshicileli:	Grayhill, Inc.
Ingcaciso yeMveliso	ROTARY ENCODER MECHANICAL 16PPR
Maxwebhu:	PDF 25BSF22-B-1-16F.pdf
RoHS Imeko	 Ukukhokela mahala / RoHS Ukuthobela
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha ze25BSF22-B-1-16F

INOMBOLO YENDAWO	25BSF22-B-1-16F
UMENZI	Grayhill, Inc.
INKCAZO	ROTARY ENCODER MECHANICAL 16PPR
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	PDF 25BSF22-B-1-16F.pdf
UKUNIKEZELA NGEEVOTSI	-
STYLE TERMINATION	PC Pin
UCHUNGECHUNGE	25
UBOMI BEHOTATIONAL (IINCLE MIN)	50K
IIPULSES NGE REVOLUTION	16
UHLOBO LOHLOBO	Binary (Absolute)
AMANYE AMAGAMA	25BSF22B116F
NGEZOBOMI	Right Angle
UHLOBO LOKUPHAKAMISA	PCB, Through Hole
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	8 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UHLOBO LWEKHOWUDI	Mechanical
UKUZIMELA	No
YAKHIWE KWISHINTSHO	No
UHLOBO LWE-ACTUATOR	1/4" Dia Flatted End

Amanqaku afanayo

Grayhill, Inc. 25BSF22-B-1-16F	Umhambisi we-25BSF22-B-1-16F	Umboneleli we-25BSF22-B-1-16F
Ixabiso le-25BSF22-B-1-16F	Imifanekiso ye-25BSF22-B-1-16F	Umfanekiso we-25BSF22-B-1-16F
Idatha ye-25BSF22-B-1-16F yePD	I-25BSF22-B-1-16F Khuphela iDatasheet	Idatha ye-25BSF22-B-1-16F
Ivenkile ye-25BSF22-B-1-16F	Thenga i25BSF22-B-1-16F	Thenga iGrayhill, Inc. 25BSF22-B-1-16F
Grayhill, Inc. 25BSF22-B-1-16F	Umboneleli we-Grayhill, Inc.	Umhambisi we-Grayhill, Inc.
Grayhill, Inc. 25BSF22-B-1-16F	Grayhill Inc. 25BSF22-B-1-16F	

Iimveliso ezihambelanayo

 <p>25BR22-G-1-16C Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 16PPR Ikhona evenkileni: 2805 pcs</p> <p>RFQ</p>	 <p>25BR22-Q-1-16C Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 16PPR Ikhona evenkileni: 2886 pcs</p> <p>RFQ</p>
 <p>25BSP10-Q-1-36C Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 36PPR Ikhona evenkileni: 2644 pcs</p> <p>RFQ</p>	 <p>25BSP11-B-1-24 Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 32PPR Ikhona evenkileni: 2194 pcs</p> <p>RFQ</p>
 <p>25BSF15-Q-1-24C Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 24PPR Ikhona evenkileni: 2266 pcs</p> <p>RFQ</p>	 <p>25BR22-B-1-16F Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 16PPR Ikhona evenkileni: 3080 pcs</p> <p>RFQ</p>
 <p>25BR400DVI-EVK Abavelisi: N/A Inkcazo: BOARD EVALUATION FOR DSR400 Ikhona evenkileni: 5557 pcs</p> <p>RFQ</p>	 <p>25BSF22-Q-1-16F Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 16PPR Ikhona evenkileni: 3097 pcs</p> <p>RFQ</p>
 <p>25BSF22-B-1-16C Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 16PPR Ikhona evenkileni: 2429 pcs</p> <p>RFQ</p>	 <p>25BSP10-Q-2-36C Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 36PPR Ikhona evenkileni: 2147 pcs</p> <p>RFQ</p>
 <p>25BSP11-B-1-16 Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 32PPR Ikhona evenkileni: 2753 pcs</p> <p>RFQ</p>	 <p>25BSF30-B-1-12C Abavelisi: Grayhill, Inc. Inkcazo: ROTARY ENCODER MECHANICAL 12PPR Ikhona evenkileni: 2929 pcs</p> <p>RFQ</p>

Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

