



Anaren

## BD60120N50100AHF

Inombolo yendawo:

BD60120N50100AHF

Umkhizizi / Umshicileli:

Anaren

Ingcaciso yeMveliso

BALUN 5.9GHZ-11.7GHZ 50/100 0404

Maxwebhu:


 BD60120N50100AHF.pdf

Umkhumbi

ehong Kong

Indlela yokuthunyelwa

DHL/Fedex/TNT/UPS/EMS




ISICELO

SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

### Iinkcukacha zeBD60120N50100AHF

INOMBOLO YENDAWO	BD60120N50100AHF
UMENZI	Anaren
INKCAZO	BALUN 5.9GHZ-11.7GHZ 50/100 0404
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	
ISHITI YEDATHA	 BD60120N50100AHF.pdf
UCHUNGECHUNGE	Xinger®
UKUBUYISELA UKULAHLEKA (MIN)	15dB
UHLU LWESIGABA	7°
IPHAKHEJI / IIMEKO	0404 (1010 Metric)
UHLOBO LOKUPHAKAMISA	Surface Mount
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
UKUFAKELA UKULAHLEKA (MAX)	0.8dB
UKUNYAMEZELA - UKUNGALINGANI / UKULINGANISELA	50 / 100 Ohm
UHLU LOLWAZI	5.9GHz ~ 11.7GHz
INKCAZO ECACILEYO	RF Balun 5.9GHz ~ 11.7GHz 50 / 100 Ohm 0404 (1010 Metric)

### Amanqaku afanayo

Anaren BD60120N50100AHF	Umhambisi we-BD60120N50100AHF	Umboneleli we-BD60120N50100AHF
Ixabiso le-BD60120N50100AHF	Imifanekiso ye-BD60120N50100AHF	Umfanekiso we-BD60120N50100AHF
Idatha ye-BD60120N50100AHF yePD	I-BD60120N50100AHF Khuphela iDatasheet	Idatha ye-BD60120N50100AHF
Ivenkile ye-BD60120N50100AHF	Thenga iBD60120N50100AHF	Thenga iAnaren BD60120N50100AHF
Anaren BD60120N50100AHF	Umboneleli we-Anaren	Umhambisi we-Anaren
Anaren BD60120N50100AHF		

### Iimveliso ezihambelanayo

 <p><b>BD6042GUL-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC CHARGE PROTECTION 9-VCSP50L1 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>BD6066GU-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC LED DRIVER CTRLR DIM VCSP85H2 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>BD60</b> Abavelisi: Carlo Gavazzi Inkcazo: DUAL 6-DIGIT LCD DISPLAY UDM60 Ikhona evenkileni: 3 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>BD6066EKN-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC LED DRIVER CTRLR DIM 28HQFN Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>BD6</b> Abavelisi: Swanstrom Tools Inkcazo: CUTTER OVAL FLSH SET STOP Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>BD6061GUT-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC LED DRIVER RGLTR 270MA 8CSP Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>BD6067GU-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC LED DRIVER RGLTR DIM VCSP85H1 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>BD6046GUL-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC CHARGE PROTECTION 13-VCSP50L2 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>BD6041GUL-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC CHARGER PROTECTION FET 9WLCSP Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>BD6040GUL-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC CHARGER PROTECTION FET 9WLCSP Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>BD6062GU-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC LED DRIVER LIN 800MA VCSP85H2 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>BD6044GUL-E2</b> Abavelisi: LAPIS Semiconductor Inkcazo: IC CHARGE PROTECTION 9-VCSP50L1 Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>

**Ilungelo lokushicilela © 2020 Umthengisi othembekileyo wezinto ze-Elektroniki- Ocean-Components.com**

I-imeyile: I-Info@Ocean-Components.com

Idilesi: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

