


IDT (Integrated Device Technology)

9DBU0931AKILF

Inombolo yendawo:
 Umkhiqizi / Umshicileli:
 Ingcaciso yeMveliso
 Maxwebhu:
 RoHS Imeko
 Umkhumbi
 Indlela yokuthunyelwa

9DBU0931AKILF
 IDT (Integrated Device Technology)
 IC BUFFER 9OUTPUT 1.5V 48MLF
[PDF 9DBU0931AKILF.pdf](#)
 Ukukhokela mahala / RoHS Ukuthobela
 ehong Kong
 DHL/Fedex/TNT/UPS/EMS



ISICELO
SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.













Iinkcukacha ze9DBU0931AKILF

INOMBOLO YENDAWO	9DBU0931AKILF
UMENZI	IDT (Integrated Device Technology)
INKCAZO	IC BUFFER 9OUTPUT 1.5V 48MLF
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	PDF 9DBU0931AKILF.pdf
UKUNIKEZELA NGEEVOTSI	1.425 V ~ 1.575 V
IPHAKHEJI YECANDELO LENKONZO	48-VFQFPN (6x6)
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKA: ISIPHUMO	1:9
PACKAGING	Tray
IPHAKHEJI / IIMEKO	48-VFQFN Exposed Pad
PLL	No
ISIPHUMO	LP-HCSL
AMANYE AMAGAMA	800-2809
UKUSHISA OKUSEBENZAYO	-40°C ~ 85°C
INANI LEESEKETHE	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	3 (168 Hours)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	12 Weeks
INJONGO EPHAMBILI	PCI Express (PCIe)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
INPUT	HCSL
UKUPHINDAPHINDA - UMAX	167MHz
UKWAHLULA - INQAKU: UMPHUMO	Yes/Yes

Amanqaku afanayo

IDT (Integrated Device Technology) 9DBU0931AKILF	Umhambisi we-9DBU0931AKILF	Umboneleli we-9DBU0931AKILF
Ixabiso le-9DBU0931AKILF	Imifanekiso ye-9DBU0931AKILF	Umfanekiso we-9DBU0931AKILF
Idatha ye-9DBU0931AKILF yePD	I-9DBU0931AKILF Khuphela iDatasheet	Idatha ye-9DBU0931AKILF
Ivenkile ye-9DBU0931AKILF	Thenga i9DBU0931AKILF	Thenga iIDT (Integrated Device Technology) 9DBU0931AKILF
IDT (Integrated Device Technology) 9DBU0931AKILF	Umboneleli we-IDT (Integrated Device Technology)	Umhambisi we-IDT (Integrated Device Technology)
IDT (Integrated Device Technology) 9DBU0931AKILF	IDT 9DBU0931AKILF	IDT (Integrated Device Technology) 9DBU0931AKILF
IDT, Integrated Device Technology Inc 9DBU0931AKILF	Integrated Device Technology (IDT) 9DBU0931AKILF	

Iimveliso ezihambelanayo

 <p>9DBU0831AKLF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 8OUTPUT 1.5V 48MLF Ikhona evenkileni: Out stock RFQ</p>	 <p>9DBU0841AKLF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 8OUTPUT 1.5V 48MLF Ikhona evenkileni: Out stock RFQ</p>
 <p>9DBU0831AKILF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 8OUTPUT 1.5V 48MLF Ikhona evenkileni: Out stock RFQ</p>	 <p>9DBU0931AKLF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 9OUTPUT 1.5V 48MLF Ikhona evenkileni: Out stock RFQ</p>
 <p>9DBV0231AKILFT Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK BUFFER Ikhona evenkileni: Out stock RFQ</p>	 <p>9DBU0941AKLF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 9OUTPUT 1.5V 48MLF Ikhona evenkileni: Out stock RFQ</p>
 <p>9DBU0741AKLF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 7OUTPUT 1.5V 40MLF Ikhona evenkileni: Out stock RFQ</p>	 <p>9DBV0231AKLF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK BUFFER 24MLF Ikhona evenkileni: Out stock RFQ</p>
 <p>9DBV0231AKILF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK BUFFER Ikhona evenkileni: Out stock RFQ</p>	 <p>9DBU0841AKILF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 8OUTPUT 1.5V 48MLF Ikhona evenkileni: Out stock RFQ</p>
 <p>9DBU0941AKILF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 9OUTPUT 1.5V 48MLF Ikhona evenkileni: 390 pcs RFQ</p>	 <p>9DBU0741AKILF Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC BUFFER 7OUTPUT 1.5V 40MLF Ikhona evenkileni: Out stock RFQ</p>