

N/A

## DRV5055A3QDBZR

Inombolo yendawo: DRV5055A3QDBZR

Umkhiziqi / Umshicileli: N/A

Ingcaciso yeMveliso: HALL EFFECT SENSOR

Maxwebhu:

Umkhumbi: ehong Kong

Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS



No Picture

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA

### Iinkcukacha zeDRV5055A3QDBZR

INOMBOLO YENDAWO	DRV5055A3QDBZR
UMENZI	N/A
INKCAZO	HALL EFFECT SENSOR
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	3 V ~ 3.63 V, 4.5 V ~ 5.5 V
TE KNOLOJI	Hall Effect
IPHAKHEJI YECANDELO LENKONZO	-
UCHUNGECHUNGE	-
UKWAHLULA	±85mT
ISIGQIBO	-
IPHAKHEJI / IIMEKO	TO-236-3, SC-59, SOT-23-3
UHLOBO LOHLOBO	Analog Voltage
UKUSHISA OKUSEBENZAYO	-40°C ~ 125°C
IXESHA LENKQUBO YENKOKELI YEHLABATHI	37 Weeks
IIMBONAKALO	Temperature Compensated
INKCAZO ECACILEYO	Hall Effect Sensor Single Axis
UKUNIKEZELWA KWANGOKU (UMAX)	10mA
I-CURRENT-OUTPUT (MAX)	1mA
BANDWIDTH	20kHz
AXIS	Single

### Amanqaku afanayo

DRV5055A3QDBZR	Umhambisi we-DRV5055A3QDBZR	Umboneleli we-DRV5055A3QDBZR
Ixabiso le-DRV5055A3QDBZR	Imifanekiso ye-DRV5055A3QDBZR	Umfanekiso we-DRV5055A3QDBZR
Idatha ye-DRV5055A3QDBZR yePD	I-DRV5055A3QDBZR Khuphela iDatasheet	Idatha ye-DRV5055A3QDBZR
Ivenkile ye-DRV5055A3QDBZR	Thenga iDRV5055A3QDBZR	Thenga i DRV5055A3QDBZR
DRV5055A3QDBZR	Umboneleli we-	Umhambisi we-

### Iimveliso ezihambelanayo

<p><b>DRV5055A1QLPG</b> Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 83149 pcs</p> <p><b>RFQ</b></p>	<p><b>DRV5055A4QDBZR</b> Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 87882 pcs</p> <p><b>RFQ</b></p>
<p><b>DRV5055A2QDBZR</b> Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 94007 pcs</p> <p><b>RFQ</b></p>	<p><b>DRV5055A1QLPGM</b> Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 67667 pcs</p> <p><b>RFQ</b></p>
<p><b>DRV5055A3QDBZT</b> Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 94688 pcs</p> <p><b>RFQ</b></p>	<p><b>DRV5055A4QLPG</b> Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 66747 pcs</p> <p><b>RFQ</b></p>
<p><b>DRV5055A2QDBZT</b> Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 92650 pcs</p> <p><b>RFQ</b></p>	<p><b>DRV5055A3QLPG</b> Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 64295 pcs</p> <p><b>RFQ</b></p>
<p><b>DRV5055A2QLPG</b> Abavelisi: N/A Inkcazo: HALL EFFECT SENSOR Ikhona evenkileni: 75526 pcs</p> <p><b>RFQ</b></p>	<p><b>DRV5055A4QDBZT</b> Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 68109 pcs</p> <p><b>RFQ</b></p>
<p><b>DRV5055A2QLPGM</b> Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 87707 pcs</p> <p><b>RFQ</b></p>	<p><b>DRV5055A3QLPGM</b> Abavelisi: N/A Inkcazo: HALL SENSOR Ikhona evenkileni: 99143 pcs</p> <p><b>RFQ</b></p>