



IDT (Integrated Device Technology)

IDT2308A-5HDC

Inombolo yendawo: IDT2308A-5HDC

Umkhqizi / Umshicileli: IDT (Integrated Device Technology)

Ingcaciso yeMveliso: IC CLOCK MULT ZD HI DRV 16-SOIC


Maxwebhu:

RoHS Imeko: Iqukethe i-lead / RoHS engahambelaniyo

Umkhumbi: ehong Kong

Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

Technology



Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA

Iinkcukacha zeIDT2308A-5HDC

INOMBOLO YENDAWO	IDT2308A-5HDC
UMENZI	IDT (Integrated Device Technology)
INKCAZO	IC CLOCK MULT ZD HI DRV 16-SOIC
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Iqukethe i-lead / RoHS engahambelaniyo
ISHITI YEDATHA	
UKUNIKEZELA NGEEVOTSI	3 V ~ 3.6 V
UHLOBO	Multiplier, Zero Delay Buffer
IPHAKHEJI YECANDELO LENKONZO	16-SOIC
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKA: ISIPHUMO	1:8
PACKAGING	Tube
IPHAKHEJI / IIMEKO	16-SOIC (0.154", 3.90mm Width)
PLL	Yes with Bypass
ISIPHUMO	LVTTTL
AMANYE AMAGAMA	2308A-5HDC
UKUSHISA OKUSEBENZAYO	0°C ~ 70°C
INANI LEESEKETHE	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Contains lead / RoHS non-compliant
INPUT	LVTTTL
UKUPHINDAPHINDA - UMAX	133MHz
UHLU LOLUNTU / UMANINZI	-
UKWAHLULA - INQAKU: UMPHUMO	No/No
ISIQENDU SENOMBOLO YESISEKO	IDT2308-5

Amanqaku afanayo

IDT (Integrated Device Technology) IDT2308A-5HDC	Umhambisi we-IDT2308A-5HDC	Umboneleli we-IDT2308A-5HDC
Ixabiso le-IDT2308A-5HDC	Imifanekiso ye-IDT2308A-5HDC	Umfanekiso we-IDT2308A-5HDC
Idatha ye-IDT2308A-5HDC yePD	I-IDT2308A-5HDC Khuphela iDatasheet	Idatha ye-IDT2308A-5HDC
Ivenkile ye-IDT2308A-5HDC	Thenga iIDT2308A-5HDC	Thenga iIDT (Integrated Device Technology) IDT2308A-5HDC
IDT (Integrated Device Technology) IDT2308A-5HDC	Umboneleli we-IDT (Integrated Device Technology)	Umhambisi we-IDT (Integrated Device Technology)
IDT (Integrated Device Technology) IDT2308A-5HDC	IDT IDT2308A-5HDC	IDT (Integrated Device Technology) IDT2308A-5HDC
IDT, Integrated Device Technology Inc IDT2308A-5HDC	Integrated Device Technology (IDT) IDT2308A-5HDC	

Iimveliso ezihambelanayo

<p>IDT2308A-4DCI8 Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD HI DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>IDT2308A-4DCI Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD STD DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>IDT2308A-5HDCI Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD HI DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>IDT2308A-3DCI8 Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD STD DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>IDT2308A-3DCI Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD STD DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>IDT2308A-5HDC8 Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD HI DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>IDT2308A-5HDCI8 Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD HI DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>IDT2308A-4DC8 Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD STD DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>IDT2308A-5HPG Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD HI DRV 16-TSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>IDT2308A-4DC Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD STD DRV 16-SOIC Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>IDT2308A-5HPGI Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD HI DRV 16-TSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>IDT2308A-5HPG8 Abavelisi: IDT (Integrated Device Technology) Inkcazo: IC CLOCK MULT ZD HI DRV 16-TSSOP Ikhona evenkileni: Out stock</p> <p>RFQ</p>

