




Aeroflex (MACOM Technology Solutions)

## MABA-009852-CF1A40

Inombolo yendawo: MABA-009852-CF1A40  
 Umkhiqizi / Umshicileli: Aeroflex (MACOM Technology Solutions)  
 Ingcaciso yeMveliso: BALUN 5MHZ-120MHZ 75/75 5SMD  
 Maxwebhu: [PDF MABA-009852-CF1A40.pdf](#)  
 RoHS Imeko:  Ukukhokela mahala / RoHS Ukuthobela  
 Umkhumbi: ehong Kong  
 Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

### Solutions



Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA













### Iinkcukacha zeMABA-009852-CF1A40

INOMBOLO YENDAWO	MABA-009852-CF1A40
UMENZI	Aeroflex (MACOM Technology Solutions)
INKCAZO	BALUN 5MHZ-120MHZ 75/75 5SMD
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	<a href="#">PDF MABA-009852-CF1A40.pdf</a>
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKA (MIN)	19dB
UHLU LWESIGABA	-
PACKAGING	Cut Tape (CT)
IPHAKHEJI / IIMEKO	5-SMD, No Lead
AMANYE AMAGAMA	1465-1696-1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UKUFAKELA UKULAHLEKA (MAX)	0.4dB
UKUNYAMEZELA - UKUNGALINGANI / UKULINGANISELA	75 / 75 Ohm
UHLU LOLWAZI	5MHz ~ 120MHz
INKCAZO ECACILEYO	RF Balun 5MHz ~ 120MHz 75 / 75 Ohm 5-SMD, No Lead

### Amanqaku afanayo

Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40	Umhambisi we-MABA-009852-CF1A40	Umboneleli we-MABA-009852-CF1A40
Ixabiso le-MABA-009852-CF1A40	Imifanekiso ye-MABA-009852-CF1A40	Umfanekiso we-MABA-009852-CF1A40
Idatha ye-MABA-009852-CF1A40 yePD	I-MABA-009852-CF1A40 Khuphela iDatasheet	Idatha ye-MABA-009852-CF1A40
Ivenkile ye-MABA-009852-CF1A40	Thenga iMABA-009852-CF1A40	Thenga iAeroflex (MACOM Technology Solutions) MABA-009852-CF1A40
Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40	Umboneleli we-Aeroflex (MACOM Technology Solutions)	Umhambisi we-Aeroflex (MACOM Technology Solutions)
Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40	Aeroflex Circuit Technology MABA-009852-CF1A40	Aeroflex MABA-009852-CF1A40
Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40	Aeroflex Metelics, Division of MACOM MABA-009852-CF1A40	M/A-Com Technology Solutions MABA-009852-CF1A40
Metelics (MACOM Technology Solutions) MABA-009852-CF1A40	MACOM Technology Solutions MABA-009852-CF1A40	

### Iimveliso ezihambelanayo

 <p><b>MABA-009210-CT17TB</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: EVAL BOARD FOR MABA-009210-CT176                  Ikhona evenkileni: 1 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>MABA-009594-CF18A0</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: BALUN 5MHZ-200MHZ 1:1 6SMD GW                  Ikhona evenkileni: 353 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>MABA-009594-CF18TB</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: EVAL BOARD FOR MABA-009594-CF18A                  Ikhona evenkileni: 2 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>MABA-010125-TC1113</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: BALUN 4.5MHZ-3GHZ 1:1 6SMD FLAT                  Ikhona evenkileni: 4 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>MABA-010441-CT38A0</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: BALUN 5MHZ-1.2GHZ 50/75 4SMD MOD                  Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>MABA-009572-CF18A0</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: BALUN 5MHZ-200MHZ 75/75 6SMD GW                  Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>MABA-009210-CT1760</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: BALUN 50MHZ-1.2GHZ 1:1 4SMD                  Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>MABA-009274-TC11T2</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: BALUN 1:1 6SMD FLAT LEAD                  Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>MABA-010129-CT4A40</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: BALUN 5MHZ-1.2GHZ 50/75 6SMD GW                  Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>MABA-010125-TC1113</b>                  Abavelisi: M/A-Com Technology Solutions                  Inkcazo: E-SERIES TRANSFORMER 4.5-3000MHZ                  Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>MABA-010245-CT1160</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: BALUN 50MHZ-1GHZ 1:1 6SMD FLAT                  Ikhona evenkileni: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>MABA-010245-CT11TB</b>                  Abavelisi: Aeroflex (MACOM Technology Solutions)                  Inkcazo: EVAL BOARD FOR MABA-010245-CT116                  Ikhona evenkileni: 3 pcs</p> <p><a href="#">RFQ</a></p>

