



Yageo



ANT1204LL05R0915A

Inombolo yendawo:	ANT1204LL05R0915A
Umkhqizi / Umshicileli:	Yageo
Ingcaciso yeMveliso	RF ANT 915MHZ CHIP SOLDER SMD
Maxwebhu:	PDF ANT1204LL05R0915A.pdf
RoHS Imeko	Ukukhokela mahala / RoHS Ukuthobela
Umkhumbi	ehong Kong
Indlela yokuthunyelwa	DHL/Fedex/TNT/UPS/EMS

ISICELO
SESIKATSHULWA

Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

Iinkcukacha zeANT1204LL05R0915A

INOMBOLO YENDAWO	ANT1204LL05R0915A
UMENZI	Yageo
INKCAZO	RF ANT 915MHZ CHIP SOLDER SMD
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Ukukhokela mahala / RoHS Ukuthobela
ISHITI YEDATHA	PDF ANT1204LL05R0915A.pdf
VSWR	2
UKUPHELISWA	Solder
UCHUNGECHUNGE	-
UKUBUYISELA UKULAHLEKELWA	-13.35dB
AMANDLA - UMAX	1W
PACKAGING	Cut Tape (CT)
AMANYE AMAGAMA	311-1525-1
INANI LAMABHANKI	1
UHLOBO LOKUPHAKAMISA	Surface Mount
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	16 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Lead free / RoHS Compliant
UKUKHUSELA I-INGRESS	-
UBUKHULU (MAX)	0.063" (1.60mm)
FUMANA	3.32dBi
UHLU LOLWAZI	905MHz ~ 925MHz
IQELA LE FREQUENCY	UHF (300 MHz ~ 1 GHz)
UKUPHINDAPHINDA (ISIKO / IBHODI)	915MHz
IIMBONAKALO	-
INKCAZO ECACILEYO	915MHz ZigBee™ Chip RF Antenna 905MHz ~ 925MHz 3.32dBi Solder Surface Mount
IZICELO	ZigBee™
UHLOBO LWE-ANTENNA	Chip

Amanqaku afanayo

Yageo ANT1204LL05R0915A	Umhambisi we-ANT1204LL05R0915A	Umboneleli we-ANT1204LL05R0915A
Ixabiso le-ANT1204LL05R0915A	Imifanekiso ye-ANT1204LL05R0915A	Umfanekiso we-ANT1204LL05R0915A
Idatha ye-ANT1204LL05R0915A yePD	I-ANT1204LL05R0915A Khuphela iDatasheet	Idatha ye-ANT1204LL05R0915A
Ivenkile ye-ANT1204LL05R0915A	Thenga iANT1204LL05R0915A	Thenga iYageo ANT1204LL05R0915A
Yageo ANT1204LL05R0915A	Umboneleli we-Yageo	Umhambisi we-Yageo
Yageo ANT1204LL05R0915A	YAGEO Corporation ANT1204LL05R0915A	

Iimveliso ezihambelanayo

<p>ANT1204F005R0915A Abavelisi: Yageo Inkcazo: RF ANT 915MHZ CHIP SOLDER SMD Ikhona evenkileni: 975 pcs RFQ</p>	<p>ANT1212B00BT2400S Abavelisi: Yageo Inkcazo: RF ANT 2.45GHZ CER PATCH SLDR Ikhona evenkileni: Out stock RFQ</p>
<p>ANT11TS33M51B Abavelisi: Dynastream Innovations Inc. Inkcazo: RF TXRX MODULE TRACE ANT Ikhona evenkileni: Out stock RFQ</p>	<p>ANT1204LL00R0918A Abavelisi: Yageo Inkcazo: RF ANT 900MHZ/1.8GHZ CHIP SLD Ikhona evenkileni: Out stock RFQ</p>
<p>ANT1204F007R0870A Abavelisi: Yageo Inkcazo: RF ANT 870MHZ CHIP SOLDER SMD Ikhona evenkileni: Out stock RFQ</p>	<p>ANT1204LL20R0433A Abavelisi: Yageo Inkcazo: RF ANT 433MHZ CHIP SOLDER SMD Ikhona evenkileni: Out stock RFQ</p>
<p>ANT1204LL08R0870A Abavelisi: Yageo Inkcazo: RF ANT 870MHZ CHIP SOLDER SMD Ikhona evenkileni: 922 pcs RFQ</p>	<p>ANT11TS33M41B Abavelisi: Dynastream Innovations Inc. Inkcazo: RF TXRX MODULE TRACE ANT Ikhona evenkileni: Out stock RFQ</p>
<p>ANT1204LL16R0870A Abavelisi: Yageo Inkcazo: RF ANT 870MHZ CHIP SOLDER SMD Ikhona evenkileni: Out stock RFQ</p>	<p>ANT1212B00FT1575S Abavelisi: Yageo Inkcazo: RF ANT 1.58GHZ CER PATCH PIN ADH Ikhona evenkileni: Out stock RFQ</p>
<p>ANT1204F002R0433A Abavelisi: Yageo Inkcazo: RF ANT 433MHZ CHIP SOLDER SMD Ikhona evenkileni: Out stock RFQ</p>	<p>ANT1212JB27B1575A Abavelisi: Yageo Inkcazo: RF ANT 1.575GHZ CER PATCH IPEX Ikhona evenkileni: 418 pcs RFQ</p>