



Avago Technologies (Broadcom Limited)

HCPL-3180

Inombolo yendawo: HCPL-3180

Umkhiziqi / Umshicileli: Avago Technologies (Broadcom Limited)

Ingcaciso yeMveliso: OPTOISO 3.75KV 1CH GATE DVR 8DIP


Maxwebhu: [HCPL-3180.pdf](#)

RoHS Imeko: Iqukethe i-lead / RoHS engahambelaniyo

Umkhumbi: ehong Kong

Indlela yokuthunyelwa: DHL/Fedex/TNT/UPS/EMS

Limited)



Umfanekiso ungabonakaliswa. Bona iinkcukacha zeenkukacha zeemveliso.

ISICELO

SESIKATSHULWA

Iinkcukacha zeHCPL-3180

INOMBOLO YENDAWO	HCPL-3180
UMENZI	Avago Technologies (Broadcom Limited)
INKCAZO	OPTOISO 3.75KV 1CH GATE DVR 8DIP
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Iqukethe i-lead / RoHS engahambelaniyo
ISHITI YEDATHA	HCPL-3180.pdf
UKUNIKEZELA NGEEVOTSI	10 V ~ 20 V
I-VOLTAGE - ISOLATION	3750Vrms
I-VOLTAGE - PHAMBILI (VF) (TYP)	1.5V
TE KNOLOJI	Optical Coupling
IPHAKHEJI YECANDELO LENKONZO	8-DIP
UCHUNGECHUNGE	-
UKUNYUKA / UKUPHELA KWEXESHA (UHLOBO)	25ns, 25ns
UKUPHAMBUKA KWEPULSE DISTORTION (MAX)	65ns
UKUSABALALISA UKULIBALA TPLH / TPHL (MAX)	200ns, 200ns
PACKAGING	Tube
IPHAKHEJI / IIMEKO	8-DIP (0.300", 7.62mm)
UKUSHISA OKUSEBENZAYO	-40°C ~ 125°C
INANI LEZITSHI	1
UHLOBO LOKUPHAKAMISA	Through Hole
INQANABA LOKUSONDEZA UBUNINZI (MSL)	1 (Unlimited)
IXESHA LENKQUBO YENKOKELI YEHLABATHI	8 Weeks
ISIMO SOBUME BENKOKELI / ISIMO SEROHS	Contains lead / RoHS non-compliant
INKCAZO ECACILEYO	2.5A Gate Driver Optical Coupling 3750Vrms 1 Channel 8-DIP
I-CURRENT-PEAK OUTPUT	2.5A
I-CURRENT-OUTPUT HIGH, LOW	2A, 2A
OKWANGOKU - DC NGOKUYA PHAMBILI (UKUBA) (MAX)	25mA
IINDLELA EZIQHELEKILEYO ZOKUNGAKHULELWA KOMZIMBA (MIN)	10kV/μs
U KWAMKELWA	CSA, UR

Amanqaku afanayo

Avago Technologies (Broadcom Limited) HCPL-3180	Umhambisi we-HCPL-3180	Umboneleli we-HCPL-3180
Ixabiso le-HCPL-3180	Imifanekiso ye-HCPL-3180	Umfanekiso we-HCPL-3180
Idatha ye-HCPL-3180 yePD	I-HCPL-3180 Khuphela iDatasheet	Idatha ye-HCPL-3180
Ivenkile ye-HCPL-3180	Thenga iHCPL-3180	Thenga iAvago Technologies (Broadcom Limited) HCPL-3180
Avago Technologies (Broadcom Limited) HCPL-3180	Umboneleli we-Avago Technologies (Broadcom Limited)	Umhambisi we-Avago Technologies (Broadcom Limited)
Avago Technologies (Broadcom Limited) HCPL-3180	Avago Technologies Limited HCPL-3180	Avago Technologies US Inc. HCPL-3180
Avago Technologies HCPL-3180	Avago Technologies (Broadcom Limited) HCPL-3180	Broadcom Limited HCPL-3180

Iimveliso ezihambelanayo

<p>HCPL-3180-300E Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 3.75KV GATE DRVR 8DIP GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>HCPL-3180-060E Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 3.75KV 1CH GATE DVR 8DIP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>HCPL-3180-360 Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 3.75KV GATE DRVR 8DIP GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>HCPL-316J-000E Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 5KV 2CH GATE DRIVER 16SO Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>HCPL-316J Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 5KV 2CH GATE DRIVER 16SO Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>HCPL-3180-060 Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 3.75KV 1CH GATE DVR 8DIP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>HCPL-316J-500E Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 5KV 2CH GATE DRIVER 16SO Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>HCPL-3180-300 Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 3.75KV GATE DRVR 8DIP GW Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>HCPL-315J-500E Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 5KV 2CH GATE DRIVER 16SO Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>HCPL-3180-000E Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 3.75KV 1CH GATE DVR 8DIP Ikhona evenkileni: Out stock</p> <p>RFQ</p>
<p>HCPL-316J#500 Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 5KV 2CH GATE DRIVER 16SO Ikhona evenkileni: Out stock</p> <p>RFQ</p>	<p>HCPL-315J-000E Abavelisi: Avago Technologies (Broadcom Limited) Inkcazo: OPTOISO 5KV 2CH GATE DRIVER 16SO Ikhona evenkileni: 975 pcs</p> <p>RFQ</p>

